

Fire Risk Assessment

Churchill Walk 14-36

Glebefields

Tipton

DY4 0SE.



Date Completed: 6th June 2024

Review Period: 3 years

Officer: A Smith Fire Risk Assessor

Checked By: J Blewitt Team Lead Fire Safety & Facilities

Current Risk Rating = Tolerable

Subsequent reviews

<u>Review date</u>	<u>Officer</u>	<u>Comments</u>

Contents

Section 0	Introduction	
Section 1	Significant Findings (executive summary)	
Section 2	People at Significant Risk of Fire	
Section 3	Contact Details	
Section 4	Description of Premises	
Section 5	Building Plan	
Section 6	External Envelope	
Section 7	Means of Escape from Fire	
Section 8	Fire Detection and Alarm Systems	
Section 9	Emergency Lighting	
Section 10	Compartmentation	
Section 11	Fire Fighting Equipment	
Section 12	Fire Signage	
Section 13	Employee Training	
Section 14	Sources of Ignition	
Section 15	Waste Control	
Section 16	Control and Supervision of Contractors and Visitors	
Section 17	Arson Prevention	
Section 18	Storage Arrangements	
Section 19	Additional Control Measures; Fire Risk Assessment – Level 2 Action Plan	
Appendix 1	Significant Hazards on Site and Information to be provided for the Fire Service Risk Rating of Block	

Section

0

Introduction

The [Regulatory Reform \(Fire Safety\) Order 2005 \(RR\(FS\)O\)](#) places a legal duty on landlords to complete a fire risk assessment (FRA). Specifically, RR(FS)O article 9. — (1) *“The responsible person must make a suitable and sufficient assessment of the risks to which relevant persons are exposed for the purpose of identifying the general fire precautions he needs to take to comply with the requirements and prohibitions imposed on him by or under this Order”*.

This fire risk assessment has been written to comply fully with the above legislation which is enforced locally by West Midlands Fire Service. If required, complaints can be made to them by telephone on 0121 380 7500 or electronically on <https://www.wmfs.net/our-services/fire-safety/#reportfiresafety>. In the first instance however, we would be grateful if you could contact us directly via [https://www.sandwell.gov.uk/info/200195/contact_the_council/283/feedb ack_and_complaints](https://www.sandwell.gov.uk/info/200195/contact_the_council/283/feedback_and_complaints) or by phone on 0121 569 6000.

The date of the fire risk assessment is on the front page, followed by any subsequent reviews. A recurring time frame is not set in legislation, but the Council will as a minimum review:

- High Risk Residential Buildings annually
- Other Buildings every 3 years

The council has procedures and policies in place that will trigger a review of the fire risk assessment. This then is recorded on the fire risk assessment. If the review suggests the fire risk assessment is not currently suitable and sufficient, then a new fire risk assessment will be undertaken and become the current fire risk assessment. The previous fire risk assessment will be retained in the building safety case for that building.


The following diagrams illustrate those procedures and persons that support the effective planning, organisation, control, monitoring and review of the preventive and protective measures. This information is provided as required under the RR(FS)O.



The above processes and procedures are overseen by the Fire Safety, Manager who reports to the Head of Building Safety

These managers attend the Building Safety and Compliance Group for scrutiny which is part of the governance structure below.

Governance Structure



To summarise the fire risk assessment, in this scenario the RR(FS)O requires the prescribed information to be recorded. The prescribed information is the significant findings of the fire risk assessment and those groups or persons especially at risk from fire. This is recorded here in [section 1](#). Also required to be recorded under article 11, are the fire safety arrangements for the planning, organisation, control, monitoring and review of the preventative and protective measures. The information shown above is part of this requirement.

Section

1

Significant findings

The significant findings (executive summary) of the fire risk assessment include those measures that have been or will be undertaken by the responsible person in order to comply with the RR(FS)O 2005.

Groups of people especially at risk of fire include such people as remote or lone workers, at risk due to layout of the building, visitors and contractors unfamiliar with the building layout as well as those with physical, sensory or mental health issues.

A third requirement that under the order must be recorded is the fire safety arrangements. This is the effective planning, organisation, control, monitoring and review of the preventive and protective measures. These are shown in the introduction.

Significant findings

Include a brief summary of protective and preventative measures where relevant along with any issues found;

The escape strategy is ‘**Stay Put Unless**’. This means in the event of a fire in your flat you should evacuate. If there is a fire elsewhere in the building you should stay put unless you are affected by fire, smoke or you have been advised by the emergency services to leave.

Section number	Section Area	Individual Risk Level
Section 6	<p>External Envelope</p> <p>Each façade of the building comprises of traditional brick masonry.</p> <p>Individual flat windows are UPVC double glazed units.</p>	<p>Trivial</p>

<p>Section 7</p>	<p>Means of Escape from Fire</p> <p>The open deck block has one staircase.</p> <p>Flat entrance doors are predominately not fire rated doors.</p> <p>Self-closing device required to flat entrance doors 24 and 32 (fire doors).</p>	<p>Tolerable</p>
<p>Section 8</p>	<p>Fire Detection and Alarm Systems</p> <p>Flats have a fire detection system fitted to an LD2 and LD3 standard.</p>	<p>Trivial</p>
<p>Section 9</p>	<p>Emergency Lighting</p> <p>No provision for emergency lighting to stair and open decks. This is deemed acceptable in this low-rise building.</p>	<p>Trivial</p>
<p>Section 10</p>	<p>Compartmentation</p> <p>The block has sufficient compartmentation between dwellings.</p>	<p>Trivial</p>
<p>Section 11</p>	<p>Fire Fighting Equipment</p> <p>The premises have no provision for firefighting equipment.</p>	<p>Trivial</p>
<p>Section 12</p>	<p>Fire Signage</p> <p>Due to simplicity of layout no requirement for fire signage.</p>	<p>Trivial</p>
<p>Section 13</p>	<p>Employee Training</p> <p>All staff receive basic fire safety awareness training.</p>	<p>Trivial</p>

Section 14	<p>Sources of Ignition</p> <p>The last test date for the fixed electrical installation was 20/01/2021.</p>	<p>Trivial</p>
Section 15	<p>Waste Control</p> <p>Refuse containers are emptied regularly.</p> <p>There is a regular cleaning service to the premises.</p>	<p>Trivial</p>
Section 16	<p>Control and Supervision of Contractors and Visitors</p> <p>Contractors are controlled centrally, and hot works permits are required where necessary.</p>	<p>Trivial</p>
Section 17	<p>Arson Prevention</p> <p>Door entry system installed.</p> <p>External lighting is in place.</p>	<p>Trivial</p>
Section 18	<p>Storage Arrangements</p> <p>Residents instructed not to bring L.P.G cylinders into block.</p>	<p>Trivial</p>

Risk Level Indicator

The following simple risk level estimator is based on commonly used risk level estimator:

Likelihood of fire	Potential consequences of fire		
	Slight harm	Moderate harm	Extreme harm
Low	Trivial risk	Tolerable risk	Moderate risk
Medium	Tolerable risk	Moderate risk	Substantial risk
High	Moderate risk	Substantial risk	Intolerable risk

Considering the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from fire (likelihood of fire) at these premises is:

Low Medium High

In this context, a definition of the above terms is as follows:

Low Unusually low likelihood of fire because of negligible potential sources of ignition.

Medium Normal fire hazards (e.g., potential ignition sources) for this type of occupancy, with fire hazards generally subject to appropriate controls (other than minor shortcomings).

High Lack of adequate controls applied to one or more significant fire hazards, such as to result in significant increase in likelihood of fire.

Considering the nature of the premises and the occupants, as well as the fire protection and procedural arrangements observed at the time of this fire risk assessment, it is considered that the consequences for life safety in the event of fire would be:

Slight Harm Moderate Harm Extreme Harm

In this context, a definition of the above terms is as follows:

Slight harm	Outbreak of fire unlikely to result in serious injury or death of any occupant (other than an occupant sleeping in a room in which a fire occurs).
Moderate harm	Outbreak of fire could foreseeably result in injury including serious injury) of one or more occupants, but it is unlikely to involve multiple fatalities.
Extreme harm	Significant potential for serious injury or death of one or more occupants.

Accordingly, it is considered that the risk to life from fire at these premises is:

Trivial Tolerable Moderate Substantial Intolerable

Comments

In conclusion, the likelihood of fire is at a medium level of risk prior to the implementation of the action plan because of the presence of normal fire hazards for this type of occupancy which have all been highlighted within the fire risk assessment.

After considering the use of the premise and the occupants the consequences for life safety in the event of a fire would be slight harm.

This is due to there being a Stay Put Unless policy and sufficient compartmentation combined with suitable smoke detection to LD2/LD3 standard within flats.

Overall, the level of risk at the time of this FRA is Tolerable.

A suitable risk-based control plan should involve effort and urgency that is proportional to risk. The following risk-based control plan is based on one that has been advocated for general health and safety risks:

Risk level	Action and timescale
Trivial	No action is required, and no detailed records need to be kept.
Tolerable	No major additional fire precautions required. However, there might be a need for reasonably practicable improvements that involve minor or limited cost.
Moderate	It is essential that efforts are made to reduce the risk. Risk reduction measures, which should take cost into account, should be implemented within a defined time period. Where moderate risk is associated with consequences that constitute extreme harm, further assessment might be required to establish more precisely the likelihood of harm as a basis for determining the priority for improved control measures.
Substantial	Considerable resources might have to be allocated to reduce the risk. If the premises are unoccupied, it should not be occupied until the risk has been reduced. If the premises are occupied, urgent action should be taken.
Intolerable	Premises (or relevant area) should not be occupied until the risk is reduced.

(Note that, although the purpose of this section is to place the fire risk in context, the above approach to fire risk assessment is subjective and for guidance only. All hazards and deficiencies identified in this report should be addressed by implementing all recommendations contained in the following action plan. The fire risk assessment should be reviewed regularly.)

Section

2

People at Significant Risk of Fire

Persons at significant risk of fire does not just refer to those people with physical, sensory or mental health issues. It also includes those at risk due to the layout or features of the building such as inner rooms or dead-end conditions. Persons may also be at risk due to remote or lone working.

The RR(FS)O requires that these people are identified in any fire risk assessment.

Sandwell Council takes the health, safety and wellbeing of its colleagues, contractors, residents and leaseholders seriously. It is our policy to exceed, where possible, the minimum health and safety requirements of the law.

Residents are responsible for letting us know whether they might need a Personal Emergency Evacuation Plan (PEEP). The Resident Engagement Officers (Fire Safety) will conduct an assessment visit upon request. Any risk-reduction measures that are found where a PEEP is necessary and completed will be documented and taken quickly. With the consent of the resident, we will make a referral for West Midlands Fire Service to conduct a Safe and Well visit.

When a PEEP is in place, the relevant information will be kept in the secure Premise Information Box (High Rise Buildings only), which is set up to help WMFS in an emergency. The data is classified as level 1, which means it complies with the General Data Protection Regulations.

Section

3

Contact Details

The Chief Executive of Sandwell Metropolitan Borough Council has ultimate responsibility for the site as the responsible person identified by the RR(FS)O 2005.

The Chief Executive has put a structure in place to support the management of the site.

This includes the role of Building Safety Manager who has duties as defined within the Regulatory Reform (Fire Safety) Order 2005.

The contact names to support the management of the site are as follows:

Chief Executive

Shokat Lal

Executive Director of Place

Alan Lunt

Assistant Director Building Compliance

Phil Deery

Fire Safety Manager

Tony Thompson

Team Lead Fire Safety

Jason Blewitt

Fire Risk Assessor(s)

Carl Hill

Louis Conway

Anthony Smith

Adrian Jones

Resident Engagement Officer - Fire Safety

Lee Mlilo

Abdul Monim Khan

Housing Office Manager

Rushpal Dhaliwal

Please note, the above details are correct at the time of the production of the risk assessment and may be subject to change

Section 4

Description of Premises

14-36
Churchill Walk
Glebefields
Tipton
DY4 0SE

Description of the Property

The property was built in 1967 and is of traditional brick construction. The property has 2 storeys inclusive of the ground floor.

The block consists of 6 ground floor flats and 6 deck access first floor flats. The block has a single staircase. Deck width is 1.6 metre and staircase width 1 metre.

The block has one main entrance to the front elevation. A door entry system with a fob reader is installed. Fire service access via a drop latch key.



The property has a pitched roof.



The communal, any workplace areas and the external envelope of the building are subject to the Regulatory Reform (Fire Safety) Order 2005 as confirmed by the Fire Safety Act 2021.

The enforcing authority is West Midlands Fire Service.

High/Low Rise	Low Rise
Number of Floors	2
Date of Construction	1967
Construction Type	Traditional brick cavity
Last Refurbished	Unknown
External Cladding	None
Number of Lifts	None
Number of Staircases	One
Automatic Smoke Ventilation to communal area	No
Fire Alarm System	No
Refuse Chute	No
Access to Roof	No. No loft hatch in communal area.
Equipment on roof (e.g., mobile phone station etc)	None.

Persons at Risk

Residents / Occupants of 12 Flats/ Maisonettes.

Visitors,

Sandwell MBC employees,

Contractors,

Service providers (e.g., meter readers, delivery people etc)

Statutory bodies (e.g., W.M.F.S, Police, and Ambulance)

**Section
5**

Building Plan

General plan which outlines the buildings footprint.



Section

6

External envelope

Following the introduction of the Fire Safety Act 2021, consideration needs to be given to the external envelope of the building for any fire risk. This predominantly means the external wall construction including any insulation filler. It also includes balconies and any other fixtures as well as doors and windows.


Below is a breakdown of the materials used within the external envelope and, as part of the external wall system.

It is deemed that the combination and application of these materials presents an acceptable level of fire risk.

- 1) The exterior of the buildings is predominantly traditional brick construction with concrete access decks at rear.



- 2) Stairs are naturally ventilated at ground and first floor as not enclosed at rear.



- 3) Front entrance doors are predominately non fire rated. This block should be considered for a door replacement programme. (See observations)



Section
7

Means of Escape from Fire

- 1) The site has one staircase that provides a means of escape.



- 2) The means of escape are protected to prevent the spread of fire and smoke. Part of this protection includes predominately non fire rated flat entrance doors (these doors will offer a level of fire protection however the fire risk assessor is unable to quantify this). Doors 24 and 32 are fire doors therefore should have a self-closing device fitted. The absence of fire doors is considered an acceptable risk as the flat entrance doors open onto an open deck at first floor and an open area at ground floor. Therefore, no smoke logging will occur, making the stay put unless policy appropriate. However, this block should be considered for a full door replacement programme. Email sent to manager of door programme.




- 3) Brickwork, on external escape route, is approx. 1300mm to bottom of window. This is deemed acceptable for a person to crouch and pass the window. Please note a stay put unless strategy applies to this building.




- 4) Electric meter cupboards are fibreglass or steel modular units fitted with budget locks, located outside.



- 5) Automatic smoke ventilation is not employed. This is acceptable as decks and stair are open to air therefore providing permanent ventilation.



- 6) Communal areas are kept free of flammable items. The communal areas are checked on a regular basis by Janitorial/ Cleaning teams. There is also an out of hours service that allows combustible items of furniture / rubbish to be removed.



Good housekeeping is fundamental to reducing risk in blocks of flats. Controlling the presence of combustibile materials and ignition sources not only reduces the potential for accidental fires to start and develop in the common parts, it also significantly reduces the scope for deliberate fires. It also ensures escape routes are free of obstructions that might hinder the evacuation of people from the building and access for fire-fighters.

- 7) Emergency lighting is not provided to this block. Adequate conventional lighting exists.



- 8) The building has sufficient passive controls that provide effective compartmentation to support a Stay Put-Unless Policy. Therefore, residents are advised to remain in their flat unless the fire directly affects them or if they are advised to evacuate by the emergency services.

- 9) Flat 30 has a porch in front of the non-fire rated entrance door. Resident confirmed at the time of the fire risk assessment that the porch door is not locked and the items within the porch will be placed within the store. Therefore, the porch is presently an acceptable risk. However, the removal of the porch is recommended when the future flat entrance door re placement programme is carried out. Resident informed of this at time of risk assessment. Email sent to housing manager in this regard.



10) Flat entrance door 24 requires a self-closing device to be refitted to this fire door.



11) Flat entrance door 32 requires a self-closing device to be fitted to this timber fire door.



12) Items of furniture were noted outside flats at ground and first floor level. Due to the residual deck widths (1.2m) and the low risk that the block presents the present situation has been deemed acceptable. Email sent to the housing manager requesting that the situation is monitored, and action taken if situation worsens.



Section

8

Fire Detection and Alarm Systems

- 1) Early warning is limited to hard wire or battery smoke alarms within each of the resident's flats. The equipment is subjected to a cyclical test.
- 2) Internal access to flats 18, 24, 30 and 32 was gained during this fire risk assessment. Fire detection installed to an LD2 and LD3 standard.
Flat 18 has smoke detection in the hall and living room.
Flat 24 has smoke detection in the hall, living room and heat detector in kitchen.
Flat 30 has a smoke detector in the hallway. As confirmed by resident (internal access not gained).
Flat 32 has a smoke detector in the hall and living room. Flat 32 has a bedroom as an inner, inner room and this has been discussed with the housing manager. L1 alarm system also requested.

For information

LD1 all rooms except wet rooms

LD2 all-risk rooms e.g., Living Room, Kitchens and Hallway.

LD3 Hallway only

- 3) There is no effective means for detecting an outbreak of fire to communal areas in the remaining blocks. The reason for this is:
 - I. Such systems may get vandalised.
 - II. False alarms would occur.
 - III. A Stay Put - Unless policy is in place.
-

Section

9

Emergency Lighting

- 1) The premises has no provision for emergency lighting. This is deemed acceptable in this low rise two storey block.

Section

10

Compartmentation

This section should be read in conjunction with Section 4

- 1) The building is designed to provide as a minimum 60-minute vertical fire resistance and 60-minute horizontal fire resistance. Please note the block is designed as open deck access therefore it is acceptable for non-fire rated windows to be adjacent to the deck.
 - 2) The premises do not have sufficient compartmentation to limit the travel and effect of smoke and flame in event of a fire in communal areas due to the open plan staircase.
 - 3) A variety of methods / materials have been used to achieve fire-stopping including Rockwool, fire rated sponge and intumescent pillows.
 - 4) The fire stopping / compartmentation is subject to an annual check by the Fire Safety Rapid Response Team.
 - 5) Any remedial works arising from the fire stopping / compartmentation check(s) will be actioned immediately by the Fire Safety Rapid Response Team.
 - 6) The building has sufficient passive controls that provide effective compartmentation to support a Stay Put -Unless policy. Therefore, residents are advised to remain in their flat unless the fire directly
-

Fire Risk Assessment

affects them or if they are advised to evacuate by the emergency services.

14-24 Churchill Walk.

Electrical		Fire Stopping Materials														Fire Stopping Materials														Fire Stopping Materials														Fire Stopping Materials														Fire Stopping Materials													
		Fire Stopping Materials				Fire Stopping Materials				Fire Stopping Materials				Fire Stopping Materials				Fire Stopping Materials				Fire Stopping Materials				Fire Stopping Materials				Fire Stopping Materials				Fire Stopping Materials				Fire Stopping Materials																																	
Floor No.	Sequels	into Staff	into Storage	into AMI Alarms	Completion of Bar	into Pinks	into Pillows	into Wipers	Blockwood	Sequels	into Staff	into Storage	into AMI Alarms	Completion of Bar	into Pinks	into Pillows	into Wipers	Blockwood	Sequels	into Staff	into Storage	into AMI Alarms	Completion of Bar	into Pinks	into Pillows	into Wipers	Blockwood	Sequels	into Staff	into Storage	into AMI Alarms	Completion of Bar	into Pinks	into Pillows	into Wipers	Blockwood	Sequels	into Staff	into Storage	into AMI Alarms	Completion of Bar	into Pinks	into Pillows	into Wipers	Blockwood	Floor No.																									
B																																															B																								
G				S																																												G																							
1																																																	1																						
2																																																		2																					
3																																																			3																				
4																																																				4																			
5																																																				5																			
6																																																				6																			
7																																																				7																			
8																																																				8																			
9																																																				9																			
10																																																					10																		
11																																																					11																		
12																																																					12																		
13																																																					13																		
14																																																					14																		
15																																																					15																		
16																																																					16																		
Common doors free from defaults		<input checked="" type="checkbox"/>		Common windows free from defaults		<input checked="" type="checkbox"/>		Flat doors free from defaults		<input checked="" type="checkbox"/>		Common cupboards locked and secure		<input checked="" type="checkbox"/>		Common areas free from traps and clutter		<input checked="" type="checkbox"/>		Common areas free from propane materials		<input checked="" type="checkbox"/>																																																	
Foam Removal & Enhancement Record										Foam, Enhancements & Other Comments:																																																													
Foam Present But Not Removed This Visit																																																																							
Foam Present & Partially Removed This Visit																																																																							
Foam Present & Fully Removed This Visit																																																																							
No Foam Present										<input checked="" type="checkbox"/>																																																													
No Enhancement Carried Out This Visit										<input checked="" type="checkbox"/>																																																													
Enhancement Carried Out This Visit										<input checked="" type="checkbox"/>																																																													



- 8) Access could not be gained into the roof space during the fire risk assessment as no access panel in communal area.



- 9) Store doors located next to flat entrance doors and to underside of staircase should be considered for upgrading works to certified FD 30s door sets during the next future works programme.



Section

11

Fire Fighting Equipment

- 1) The premise has no provision for firefighting equipment.

Section

12

Fire Signage

- 1) Fire Action Notices are not displayed throughout the building. The signs are not necessary due to the building not having a complex layout.
- 2) Smoking is prohibited within any communal parts of the building in line with Smoke Free England Legislation.



- 3) Yellow LPG warning signs are not displayed.
-

**Section
13**

**Employee & Resident
Training/Provision of Information**

- 1) All Caretaking / Cleaning Employees have undertaken fire safety training. This includes use of bespoke 'Fire Safety in High / Low Rise Flatted Accommodation' Video.
- 2) All employees are encouraged to complete 'In the line of fire' training on an annual basis.
- 3) Caretaking Teams are not currently trained in the effective use of fire extinguishers. Caretaking Teams are not expected to tackle fires in this area.
- 4) Staff undertaking fire risk assessments are qualified to or working towards Level 4 Diploma in Fire Safety.
- 5) Fire safety information has been provided as part of tenancy pack.
- 6) Information regarding use of fire doors is provided to residents.



- 7) Information regarding the Stay Put unless fire evacuation strategy is provided to residents.



**Section
14**

Sources of Ignition

- 1) Smoking is prohibited within any communal parts of the building in line with Smoke Free England legislation. Evidence of smoking was witnessed. Email sent to housing manager requesting residents are reminded that smoking is prohibited.
- 2) Hot working is not normally carried out. If essential maintenance requires the use of hot work processes, then corporate policies and procedures are to be followed.
- 3) Portable electrical equipment used as part of the Caretaking / Cleaning regime is subject to annual PAT Testing. This information is held by the Estate Services Manager Bryan Low.
- 4) The fixed electrical installation shall be tested every 5 years. Last test January 2021.



- 5) Portable heaters are not allowed in any common parts of the premises.
- 6) Gas appliances and pipework (where installed) are subject to annual testing and certification. This cyclical contract is managed by the in-house Gas Team. Gas supply is external.



Section 15

Waste Control

- 1) There is a regular cleaning service to the premises.
- 2) Regular checks by Caretakers minimise risk of waste accumulation.



- 3) There is an 'Out of Hours' service in place to remove bulk items.

Section 16

Control and Supervision of Contractors and Visitors

- 1) Responsive Repairs service delivered by Sandwell MBC necessitates the production of an order via the computerised repairs system. Details of any known risks are documented on the repair order.
 - 2) Hot works are not permitted unless authorisation is given via the approved officer. The hot works procedure is to be followed.
 - 3) Owing to the nature of Low-Rise flatted accommodation, it is difficult to manage / control individual contractors / utility companies.
-

- 4) However, utility companies are not allowed to access any service cupboard or secure area. They must request and collect maintenance keys from the local housing team. This allows scrutiny of what is the scope of any works such as installation of tenant's broadband / phone line etc.
- 5) Where contractors are appointed to undertake major refurbishment works, Sandwell MBC Urban Design team will put control measures in place. Such Measures include: -
 - a) Pre-Contract Meetings – where contractor is made aware of all working arrangements and safe systems of work to be adopted. Issues covered in this meeting will include:
 - Health and Safety.
 - Site security.
 - Safety of working and impact on children/school business.
 - Fire risk, if any.
 - Site Emergency Plan.
 - b) Monthly Site Meetings – in order to monitor, review and share any new information including any new risks.
 - c) Site monitored daily whilst work is in progress by Clerk of Works / Health and Safety Officers.
 - d) Final Contractor review on completion of works undertaken.

Section

17

Arson Prevention

- 1) Regular checks are undertaken by Janitorial / Cleaning Teams which helps reduce the risk of arson.
 - 2) There is no current evidence of arson.
 - 3) The perimeter of the premises is well illuminated.
 - 4) There have been no fire related incidents since the previous FRA.
-

Section
18

Storage Arrangements

- 1) Residents instructed not to bring L.P.G cylinders into block.
 - 2) The tenancy conditions, Section 7 – Condition 5.6 stipulates “If you live in a flat or maisonette, you, people living with you and any visitors to your property must not keep or use paraffin oil, petrol, bottled gas appliances or any other explosive, FLAMMABLE or dangerous material in the property. This restriction also applies to any storage facility situated in or attached to the block, which has been provided for your use.”
 - 3) No Flammable liquids stored on site by Caretakers / cleaners.
 - 4) There are no flammable liquids or gas cylinders stored on site.
-

**Section
19**

**Additional Control Measures;
Fire Risk Assessment - Level 2
Action Plan**

Significant Findings

Action Plan

It is considered that the following recommendations should be implemented to reduce fire risk to, or maintain it at, the following level:

Trivial Tolerable

Definition of priorities (where applicable):

P1 Arrange and complete as urgent – Within 10 days

P2 Arrange and complete within 1-3 Months of assessment date

P3 Arrange and complete within 3-6 Months of assessment date

P4 Arrange and complete exceeding 6 months under programmed work



Fire Risk Assessment Level 2 Action Plan



Name of Premises or Location:


Churchill Walk 14-36

Date of Action Plan:


07/06/2024

Review Date:

<Insert date>

Question/ Ref No	Required Action	Supporting photograph	Priority	Timescale and Person Responsible	Date Completed
7/10	Self-closing device required to entrance door (fire door) of flat 24.		P3	Fire Rapid Response 3-6 Months	

Fire Risk Assessment

7/11	Self -closing device required to entrance door (fire door) of flat 32		P3	Fire Rapid Response 3-6 Months	
------	---	--	----	-----------------------------------	--

When undertaking future improvement program(s), it is advised that the observations listed below should be given consideration (noting that the safety of the residents is not jeopardised by these, and all steps to reduce any known risks have been taken).


Observations

Future works programme should consider replacing the store doors adjacent to flat entrance doors and under the staircase to certified FD 30S door sets.



Fire Risk Assessment



Future works programme should consider the installation of emergency lighting to staircase and decks.



Future flat entrance door replacement programme (to certified self-closing FD 30S Door sets) required for this block. Email sent to manager of door programme.



Signed

	Fire Risk Assessor	Date: 07/06/2024
	Quality Assurance Check	Date: 10/06/2024



Significant Hazards on Site and Information to be Provided for the Fire Service

Name of property: Churchill Walk 14-36




Updated: 08/07/2022

Premise Manager: Tony Thompson

Tel. No.: 0121 569 2975

Hazard	Information/Comments
Asbestos	An asbestos survey has been undertaken of the communal areas. Survey held by Sandwell Housing (Derek Still Tel:- 0121 569 5077). <i>Include survey</i>

14-24 Churchill Walk



Asbestos Survey		Property Address	14-24 Churchill Walk, Tipton, DY4 0SE		Office use <input checked="" type="checkbox"/>
Surveyed by	D Jones	Date	14/03/2014	Checked by	DEREK STILL
Reason for request		HSG 264 - Survey Report Type		Date	18/05/2020
Investment Void		Refurbishment Survey		Property Description Low Rise Flats  Year Built: 1967	
Investment Tenanted		Management Survey	<input checked="" type="checkbox"/>		
R & M Void		SHAPE Interrogated.	<input checked="" type="checkbox"/>		
R & M Tenanted		No Existing SHAPE Data.			
Medical / Emergency - Heating Works		Existing SHAPE Data.	<input checked="" type="checkbox"/>		
Communal Areas	<input checked="" type="checkbox"/>	Refurb Surveys Interrogated ?			
Notes / including details of similar property surveys completed. Main roof verge cloaking may have asbestos material encapsulated by existing dry verge system. **Survey reviewed by W Colbourne on 28/07/16 ** Revised by S. Hamson – 08/07/2022.					
				Building Surveyors 0121 569 5077 Asset Team – Investment Division Operations & Development Centre Roway Lane Oldbury B69 3ES 	


Fire Risk Assessment

Sample Locations	Property Address	14-24 Churchill Walk, Tipton, DY4 0SE						
LOCATION	MATERIAL	QTY	SURFACE TREATMENT	SAMPLE REF	RESULT	HSE NOTIFY	Labelled?	ACTION TAKEN ON CONTRACT
IF DURING THE COURSE OF WORK SUSPECTED ACM'S ARE IDENTIFIED THAT ARE NOT CONTAINED WITHIN THIS REPORT STOP WORK & SEEK ADVICE								
FIRST FLOOR COMMUNAL LANDING SOFFIT	CEMENT	-	SEALED	DS8121	CHRYSOTILE	NO	NO	
MAIN ROOF SOFFIT	CEMENT	-	SEALED	DS8121	CHRYSOTILE	NO	NO	
FIRST FLOOR COMMUNAL LANDING FLOORS	ASPHALT	-	-	-	-	-	-	REQUEST SAMPLE IF TO BE DISTURBED
DAMP PROOF COURSE	BITUMINOUS	-	-	-	-	-	-	REQUEST SAMPLE IF TO BE DISTURBED
16 FRONT DOOR – FRAME SEALANT	MASTIC	-	SEALED	SH 1116 / 001	NO ASBESTOS DETECTED	-	-	-
ITEMS SHOWN BELOW HAVE BEEN ASSESSED ON SITE BY THE ASBESTOS SURVEYOR & ARE CONFIRMED NOT TO BE ACM'S.								
LOCATION DESCRIPTION	MATERIAL	LOCATION DESCRIPTION	MATERIAL	LOCATION DESCRIPTION	MATERIAL			
OUTHOUSE ROOF	MINERAL FELT	FRONT DOOR ENTRY – FRAME SEALANT	SILICONE					
FRONT DOOR FRAMES TO 18, 22 AND 24 – FRAME SEALANT	SILICONE							
FRONT DOOR FRAMES TO 14 AND 20	NO VISIBLE SEALANT							
STORE CUPBOARD DOOR FRAMES TO 16, 18 AND 22	NO VISIBLE SEALANT							
UNDER STAIRS STORE CUPBOARD DOOR FRAME	NO VISIBLE SEALANT							

Fire Risk Assessment

26-36 Churchill Walk

Asbestos Survey		Property Address		26-36 Churchill Walk, Tipton, DY4 0SE		✓ Office use			
Surveyed by		D Jones		Date		14/03/2014			
Checked by		DEREK STILL		Desktop Check		✓			
Site Check									
Reason for request		HSG 264 - Survey Report Type		Date		18/05/2020			
Investment Void		Refurbishment Survey		Property Description Low Rise Flats 					
Investment Tenanted		Management Survey						✓	
R & M Void		SHAPE Interrogated.						✓	
R & M Tenanted		No Existing SHAPE Data.							
Medical / Emergency - Heating Works		Existing SHAPE Data.						✓	
Communal Areas		✓ Refurb Surveys Interrogated ?							
				Year Built		1967			
Notes / including details of similar property surveys completed.									
Main roof verge cloaking may have asbestos material encapsulated by existing dry verge system.									
**Survey reviewed by W Colbourne on 28/07/16 **									
Revised by S. Harrison – 08/07/2022									
Building Surveyors 0121 569 5077				Asset Team – Investment Division Operations & Development Centre Roway Lane Oldbury B69 3ES					
									



Sample Locations		Property Address		26-36 Churchill Walk, Tipton, DY4 0SE				
LOCATION	MATERIAL	QTY	SURFACE TREATMENT	SAMPLE REF	RESULT	HSE NOTIF Y	Labelled ?	ACTION TAKEN ON CONTRACT
IF DURING THE COURSE OF WORK SUSPECTED ACM'S ARE IDENTIFIED THAT ARE NOT CONTAINED WITHIN THIS REPORT STOP WORK & SEEK ADVICE								
FIRST FLOOR COMMUNAL LANDING SOFFIT	CEMENT	-	SEALED	D98121	CHRYSOTILE	NO	NO	
MAIN ROOF SOFFIT	CEMENT	-	SEALED	D98121	CHRYSOTILE	NO	NO	
FIRST FLOOR COMMUNAL LANDING FLOORS	ASPHALT	-	-	-	-	-	-	REQUEST SAMPLE IF TO BE DISTURBED
DAMP PROOF COURSE	BITUMINOUS	-	-	-	-	-	-	REQUEST SAMPLE IF TO BE DISTURBED
32 FRONT DOOR – FRAME SEALANT	MASTIC	-	SEALED	SH 1117 / 001	NO ASBESTOS DETECTED	-	-	-
30 DOOR / COMBINATION FRAME	-	-	-	-	NOT SAMPLED	-	-	FITTED BY LEASEHOLDER
ITEMS SHOWN BELOW HAVE BEEN ASSESSED ON SITE BY THE ASBESTOS SURVEYOR & ARE CONFIRMED NOT TO BE ACM'S.								
LOCATION DESCRIPTION	MATERIAL	LOCATION DESCRIPTION	MATERIAL	LOCATION DESCRIPTION	MATERIAL			
OUTHOUSE ROOF	MINERAL FELT							
FRONT DOOR FRAMES TO 26 AND 28 – FRAME SEALANT	SILICONE							
FRONT DOOR FRAMES TO 30, 34 AND 36	NO VISIBLE SEALANT							
STORE CUPBOARD DOOR FRAMES TO 28, 30, 32, 34 AND 36	NO VISIBLE SEALANT							
FRONT DOOR ENTRY – FRAME SEALANT	SILICONE							

Fire Risk Assessment
