

Fire Risk Assessment

Farley Street



**97 – 128, Farley Street
Tipton,
DY4 7LA.**

Date Completed: 19/09/2024.

Review Period: 12 months.

Officer: A. Jones Fire Risk Assessor.

Checked By: L. Conway Fire Risk Assessor.

Current Risk Rating = Tolerable

Subsequent reviews

<u>Review date</u>	<u>Officer</u>	<u>Comments</u>

Contents

Section 0	Introduction	
Section 1	Significant Findings (executive summary)	
Section 2	People at Significant Risk of Fire	
Section 3	Contact Details	
Section 4	Description of Premises	
Section 5	Building Plan	
Section 6	External Envelope	
Section 7	Means of Escape from Fire	
Section 8	Fire Detection and Alarm Systems	
Section 9	Emergency Lighting	
Section 10	Compartmentation	
Section 11	Fire Fighting Equipment	
Section 12	Fire Signage	
Section 13	Employee Training	
Section 14	Sources of Ignition	
Section 15	Waste Control	
Section 16	Control and Supervision of Contractors and Visitors	
Section 17	Arson Prevention	
Section 18	Storage Arrangements	
Section 19	Additional Control Measures. Fire Risk Assessment – Action Plan	
Appendix 1	Significant Hazards on Site and Information to be provided for the Fire Service Risk Rating of Block	

Section

0

Introduction

The [Regulatory Reform \(Fire Safety\) Order 2005 \(RR\(FS\)O\)](#) places a legal duty on landlords to complete a fire risk assessment (FRA). Specifically, RR(FS)O article 9. — (1) *“The responsible person must make a suitable and sufficient assessment of the risks to which relevant persons are exposed for the purpose of identifying the general fire precautions he needs to take to comply with the requirements and prohibitions imposed on him by or under this Order”*.

This fire risk assessment has been written to comply fully with the above legislation which is enforced locally by West Midlands Fire Service. If required, complaints can be made to them by telephone on 0121 380 7500 or electronically on <https://www.wmfs.net/our-services/fire-safety/#reportfiresafety>. In the first instance however, we would be grateful if you could contact us directly via [https://www.sandwell.gov.uk/info/200195/contact_the_council/283/feedb ack_and_complaints](https://www.sandwell.gov.uk/info/200195/contact_the_council/283/feedback_and_complaints) or by phone on 0121 569 6000.


The date of the fire risk assessment is on the front page, followed by any subsequent reviews. A recurring time frame is not set in legislation, but the Council will as a minimum review:

- High Risk Residential Buildings annually
- Other Buildings every 3 years

The council has procedures and policies in place that will trigger a review of the fire risk assessment. This then is recorded on the fire risk assessment. If the review suggests the fire risk assessment is not currently suitable and sufficient, then a new fire risk assessment will be undertaken and become the current fire risk assessment. The previous fire risk assessment will be retained in the building safety case for that building.

The following diagrams illustrate those procedures and persons that support the effective planning, organisation, control, monitoring, and review of the preventive and protective measures. This information is provided as required under the RR(FS)O.


Fire Risk Assessment



The above processes and procedures are overseen by the Fire Safety, Manager who reports to the Head of Building Safety

These managers attend the Building Safety and Compliance Group for scrutiny which is part of the governance structure below.

Governance Structure



To summarise the fire risk assessment, in this scenario the RR(FS)O requires the prescribed information to be recorded. The prescribed information is the significant findings of the fire risk assessment and those groups or persons especially at risk from fire. This is recorded here in [Section 1](#). Also required to be recorded under article 11, are the fire safety arrangements for the planning, organisation, control, monitoring, and review of the preventative and protective measures. The information shown above is part of this requirement.

Section

1

Significant findings

The significant findings (executive summary) of the fire risk assessment include those measures that have been or will be undertaken by the responsible person in order to comply with the RR(FS)O 2005.

Groups of people especially at risk of fire include such people as remote or lone workers, at risk due to layout of the building, visitors, and contractors unfamiliar with the building layout as well as those with physical, sensory, or mental health issues.

A third requirement that under the order must be recorded is the fire safety arrangements. This is the effective planning, organisation, control, monitoring, and review of the preventive and protective measures. These are shown in the introduction.

Significant findings

Include a brief summary of protective and preventative measures where relevant along with any issues found.

The escape strategy is '**Stay Put Unless**'. This means in the event of a fire in your flat you should evacuate. If there is a fire elsewhere in the building you should stay put unless you are affected by fire, smoke or you have been advised by the emergency services to leave.

Section number	Section Area	Individual Risk Level
Section 6	<p>External Envelope Side elevations have Wetherby mineral wool silicone render system – A2 fire classification.</p> <p>Masonry finish to the front and rear.</p> <p>Individual balconies to flats are cantilevered concrete with a steel and glass balustrade.</p> <p>Exterior window frames are powdered coated aluminium.</p>	Trivial

<p>Section 7</p>	<p>Means of Escape from Fire There are 2 protected staircase's that provide a sufficient means of escape.</p> <p>All communal doors along the means of escape are self-closing notional fire doors upgraded with combined intumescent strips / cold smoke seals.</p> <p>There are 2 final exit doors.</p> <p>The front entrance door to Flat 115 had been temporary repaired and was noted in the previous FRA. This should be replaced as soon as practicable.</p>	<p>Tolerable</p>
<p>Section 8</p>	<p>Fire Detection and Alarm Systems Fire detection within flats is installed to a combination of LD2 & LD3 standard.</p> <p>Automatic opening vents are installed to the rear stairwell on the 7th floor only.</p> <p>Louvre vents provide natural ventilation to all landings of the front staircase.</p> <p>A deluge system is provided to the bin store.</p>	<p>Trivial.</p>
<p>Section 9</p>	<p>Emergency Lighting The premises have a sufficient emergency / escape lighting system.</p>	<p>Trivial</p>
<p>Section 10</p>	<p>Compartmentation The building is designed to provide as a minimum 1-hour vertical fire resistance and 1-hour horizontal fire resistance around flats stairwells and lift shafts.</p> <p>All doors are FD30s doors with intumescent strips & cold smoke seals, including those in 1-hour rated walls.</p> <p>Flat 122 has a missing outer letterplate.</p>	<p>Tolerable</p>

<p>Section 10 (Cont'd)</p>	<p>The access panel at the side of the front door of flat 122 needs to be sealed with intumescent materials.</p> <p>7th floor by flat 126 – Landing door warped towards head, requires replacement FD30s. Outstanding from previous Fire risk Assessment.</p> <p>7th floor by flat 128 – landing door warped and requires replacement FD30s. Outstanding from previous Fire risk Assessment.</p>	
<p>Section 11</p>	<p>Fire Fighting Equipment There is a fire hydrant adjacent the front main entrance.</p> <p>The dry riser serves all floors.</p> <p>There is a C02 fire extinguisher within the lift motor room.</p> <p>There is a deluge system in the bin store.</p> <p>Maintenance contracts are in place to service the dry riser twice yearly and the fire extinguisher annually.</p>	<p>Trivial</p>
<p>Section 12</p>	<p>Fire Signage Generally, signage is adequate throughout the building.</p> <p>However, on the ground floor the exit signage was non-compliant due to no directional arrow being displayed. This has been replaced following the assessment.</p>	<p>Tolerable</p>
<p>Section 13</p>	<p>Employee Training All staff receive basic fire safety awareness training.</p>	<p>Trivial</p>
<p>Section 14</p>	<p>Sources of Ignition The fixed electric tests should be done every 5 years. The last test date was 19/10/2023.</p>	<p>Trivial</p>

Section 15	Waste Control Regular checks by Caretakers minimise risk of waste accumulation. Refuse containers are secured within the bin store.	Trivial
Section 16	Control and Supervision of Contractors and Visitors Contractors are controlled centrally, and hot works permits are required where necessary.	Trivial
Section 17	Arson Prevention A door entry system prevents unauthorised access. Perimeter lighting is in place.	Trivial
Section 18	Storage Arrangements There are no storage facilities for residents within the communal areas. Residents instructed not to bring L.P.G cylinders into block.	Trivial

Risk Level Indicator

The following simple risk level estimator is based on commonly used risk level estimator:

Likelihood of fire	Potential consequences of fire		
	Slight harm	Moderate harm	Extreme harm
Low	Trivial risk	Tolerable risk	Moderate risk
Medium	Tolerable risk	Moderate risk	Substantial risk
High	Moderate risk	Substantial risk	Intolerable risk

Considering the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from fire (likelihood of fire) at these premises is:

Low Medium High

In this context, a definition of the above terms is as follows:

Low Unusually low likelihood of fire because of negligible potential sources of ignition.

Medium Normal fire hazards (e.g. potential ignition sources) for this type of occupancy, with fire hazards generally subject to appropriate controls (other than minor shortcomings).

High Lack of adequate controls applied to one or more significant fire hazards, such as to result in significant increase in likelihood of fire.

Considering the nature of the premises and the occupants, as well as the fire protection and procedural arrangements observed at the time of this fire risk assessment, it is considered that the consequences for life safety in the event of fire would be:

Slight Harm Moderate Harm Extreme Harm

In this context, a definition of the above terms is as follows:

Slight harm Outbreak of fire unlikely to result in serious injury or death of any occupant (other than an occupant sleeping in a room in which a fire occurs).

Moderate harm Outbreak of fire could foreseeably result in injury including serious injury) of one or more occupants, but it is unlikely to involve multiple fatalities.

Extreme harm Significant potential for serious injury or death of one or more occupants.

Accordingly, it is considered that the risk to life from fire at these premises is:

Trivial Tolerable Moderate Substantial Intolerable

Comments

In conclusion, the likelihood of a fire is at a medium level of risk prior to the implementation of the action plan because of the potential fire hazards that have been highlighted within the risk assessment, including actions points from the previous FRA that have not been addressed.

After considering the use of the premise and the occupants within the block, the consequences for life safety in the event of a fire would be slight harm.

This is due to there being sufficient compartmentation to include FD30s composite doors to flat entrances, notional 30 minute fire doors upgraded with intumescent strips and cold smoke seals to communal doors and service cupboards, combined with suitable smoke detection to LD2 & LD3 standard within flats, 2 protected staircases, automatic smoke ventilation, and a Stay Put – Unless policy.

Overall, the level of risk at the time of this FRA is tolerable, this can be lowered to trivial once recommended actions have been completed.

A suitable risk-based control plan should involve effort and urgency that is proportional to risk. The following risk- based control plan is based on one that has been advocated for general health and safety risks:

Risk level	Action and timescale
Trivial	No action is required, and no detailed records need to be kept.
Tolerable	No major additional fire precautions required. However, there might be a need for reasonably practicable improvements that involve minor or limited cost.
Moderate	It is essential that efforts are made to reduce the risk. Risk reduction measures, which should take cost into account, should be implemented within a defined time period. Where moderate risk is associated with consequences that constitute extreme harm, further assessment might be required to establish more precisely the likelihood of harm as a basis for determining the priority for improved control measures.
Substantial	Considerable resources might have to be allocated to reduce the risk. If the premises are unoccupied, it should not be occupied until the risk has been reduced. If the premises are occupied, urgent action should be taken.
Intolerable	Premises (or relevant area) should not be occupied until the risk is reduced.

(Note that, although the purpose of this section is to place the fire risk in context, the above approach to fire risk assessment is subjective and for guidance only. All hazards and deficiencies identified in this report should be addressed by implementing all recommendations contained in the following action plan. The fire risk assessment should be reviewed regularly.)

Section

2

People at Significant Risk of Fire

Persons at significant risk of fire does not just refer to those people with physical, sensory, or mental health issues. It also includes those at risk due to the layout or features of the building such as inner rooms or dead-end conditions. Persons may also be at risk due to remote or lone working.

The RR(FS)O requires that these people are identified in any fire risk assessment.

Sandwell Council takes the health, safety and wellbeing of its colleagues, contractors, residents, and leaseholders seriously. It is our policy to exceed, where possible, the minimum health and safety requirements of the law.

Residents are responsible for letting us know whether they might need a Personal Emergency Evacuation Plan (PEEP). The Resident Engagement Officers (Fire Safety) will conduct an assessment visit upon request. Any risk-reduction measures that are found where a PEEP is necessary and completed will be documented and taken quickly. With the consent of the resident, we will make a referral for West Midlands Fire Service to conduct a Safe and Well visit.

When a PEEP is in place, the relevant information will be kept in the secure Premise Information Box (High Rise Buildings only), which is set up to help WMFS in an emergency. The data is classified as level 1, which means it complies with the General Data Protection Regulations.

Section

3

Contact Details

The Chief Executive of Sandwell Metropolitan Borough Council has ultimate responsibility for the site as the responsible person identified by the RR(FS)O 2005.

The Chief Executive has put a structure in place to support the management of the site. This includes the role of Building Safety Manager who has duties as defined within the Regulatory Reform (Fire Safety) Order 2005.

The contact names to support the management of the site are as follows:

Chief Executive

Shokat Lal

Directorate of Place

Alan Lunt

Assistant Director Building Compliance

Phil Deery

Fire Safety Manager

Tony Thompson

Team Lead Fire Safety

Jason Blewitt

Fire Risk Assessor(s)

Adrian Jones

Anthony Smith

Carl Hill

Louis Conway

Resident Engagement Officer - Fire Safety

Abdul Monim Khan

Lee Mlilo

Housing Office Manager

Rushpal Dhaliwal

Please note, the above details are correct at the time of the production of the risk assessment and may be subject to change

Section 4

Description of Premises

97 - 128 Farley Street
Tipton
West Midlands
DY4 7LA.

Description of the Property

The communal, any workplace areas and the external envelope of the building are subject to the Regulatory Reform (Fire Safety) Order 2005 as confirmed by the Fire Safety Act 2021.

The enforcing authority is West Midlands Fire Service.

This high-rise block was constructed in approximately 1960 of Waites concrete/brick construction surmounted by a flat concrete roof.

The side elevations were clad with a Wetherby mineral wool, silicon render system, fire classification A2 during a 2009 refurbishment.

The front and rear elevations are traditional masonry with no cladding.

With regard to the external façade, the materials, construction, and their constituent properties have been taken from a database provided by Sandwell Metropolitan Borough Council.



The block consists of 8 storeys (inclusive of the ground floor) with four dwellings to each floor.



The block has a main entrance/exit to the front elevation and a further entrance/exit located on the rear elevation.



Both entrances have a door entry system with a fob reader installed. The front entrance only, has a firefighter door override switch by use of a drop latch key.



There are two protected staircases and a single lift car that serve all floors.



Access to the lift motor room is obtained via a ceiling hatch from the 7th floor lobby. The access ladder is stored within the 7th floor dry riser cupboard. Keys to the riser cupboard & the padlocks on the ceiling hatch are in the firefighter's white box.



Access to the flat roof is via a door within the lift motor room.



There is a single waste disposal chute accessed on all floors within the front staircase. The bin store is right of the main entrance. Key is stored in the firefighter's white box.




The building safety notice is displayed in the ground floor lobby.



Service cupboards containing resident's electricity meters are in each lift lobby.



On arrival Information (for WMFS)



There is a firefighter's white box externally to the left-hand side of the main entrance to the front of the building. The box contains keys for the building and is secured with a bridge-door padlock.



Access is gained via the firefighter's door override switch utilising the drop latch key in the white box.




There is a Secure Premise Information Box (PIB) located in the ground floor rear entrance lobby. It is a Gerda box that utilises a standard WMFS suited key. The PIB contains floor plans, vertical plans, orientation plans, information for WMFS and documents for those with vulnerabilities who may require additional consideration if there is a fire incident (PEEP).



There is a firefighter's lift override switch to the right-hand side of the lift car. This is operated by the drop latch key.




The dry riser inlet is next to the ground floor lift car. Access is gained utilising the suited 54 key, also contained in the white box.



Dry riser outlets are available on each floor within the secured cupboards next to the lift car. Each outlet is secured in the off position by cable tie.



Automatic opening vents are installed to the 7th floor rear staircase. The override switch is on the 7th floor landing wall.



Natural ventilation is employed to the front staircase via a louvred vents on all floor landings.



Fire Risk Assessment

Address: Block 97-128 Farley Street DY4 7LA		Survey date: 18/09/2024	ON ARRIVAL INFORMATION
BUILDING LAYOUT			
Building height	21.6 metres		
Construction	Wates, concrete brick		
Number of floors	8 including ground floor		
Layout	<p>The block consists of 8 storeys (inclusive of the ground floor). Each of the floors contains 4 number dwellings, Lift granting access up to the 7th floor, aluminium ladders stored in the 7th floor storage cupboard grants access to the lift motor room via a trap door. A full height door then grants access to the main roof.</p> <p>2 sets of staircases granting access to all 8 floors of the block located at the front and rear of the block.</p> <p>Corridors and stairs are protected by FD30s doors.</p> <p>2 sets of ingress / egress points to the block with the override switch, FWB and fire hydrant located nearest the MAP (main access point)</p>		
Lifts	1		
Types of entrance doors	Individual flat doors are FD30s of composite construction. Communal doors within the block are notional timber FD30s		
Rubbish chutes/ bin rooms	Yes		
Common voids	No		
Access to roof/ service rooms	Aluminium ladder (stored in dry riser 7 th floor cupboard) gives access into motor room through a trap (top floor landing). A full height door then allows access onto the main roof.		
Occupants	Approx. 68 based on an average of 2 occupants per flats (32 flats)		
Evacuation strategy	Stay Put Unless- The escape strategy is 'Stay Put Unless'. This means in the event of a fire in your flat you should evacuate. If there is a fire elsewhere in the building you should stay put unless you are affected by fire or smoke		
Fire alarm/ evacuation alarm	Early warning is limited to hard wired or battery smoke alarms within each of the resident's flats.		
Caretaker/ concierge	Caretaking/cleaning service that conducts regular checks of the building		
FIREFIGHTING SYSTEMS			
Water supplies	Fire hydrant is located at the entrance of the building, fire hydrant location/ water isolation points located on the orientation plan, there is a dry riser that serves the building outlets located on the floor plans.		
Fire mains	The dry riser inlet is located within the ground floor dry riser cupboard (twin valve) secured with a type 54 suited mortice lock.		
Firefighting shafts	No firefighting lifts/shafts however there is the ability to take control of the common lift. A Firefighter lift control switch is located within the ground floor lobby		
Smoke control vents	Automatic smoke ventilation is employed to the head of the rear staircase, <u>There</u> is master reset / control switch located on the 7 th floor rear staircase landing. The front staircase is naturally ventilated by louvres to all floors. Communal windows (other than smoke vents) can be opened without the need for a key.		
Sprinkler system	A water suppression system is provided to the refuse chute bin store		
DANGEROUS SUBSTANCES			
Location, type, and quantity	<p>ALL BALCONIES – RAINWATER PIPE – CEMENT- SEALED – PRESUMED – CHRYSOTILE</p> <p>FLAT ROOF MINERAL FELT TO LIFT MOTOR-FRONT AND REAR ENTRANCES – BITUMINOUS</p>		
SERVICES			
Electricity	Electric meter cupboards located on each floor of the block		
Gas	Gas isolation within individual flats.		

High/Low Rise	High
Number of Floors	8
Date of Construction	1960
Construction Type	Wates Concrete / Brick
Last Refurbished	2009
External Cladding	Front and rear elevations have no cladding (still original brickwork. Gable walls have Wetherby Mineral wool silicone render system (fire rating A2)
Number of Lifts	One
Number of Staircases	Two
Automatic Smoke Ventilation to communal area	Yes – 7 th floor rear staircase. Louvre vents to front staircase.
Fire Alarm System	No
Refuse Chute	Yes
Access to Roof	Aluminium ladder (stored in dry riser) gives access into motor room through a trap (top floor landing). A full height door then allows access onto the main roof
Equipment on roof (e.g. mobile phone station etc)	No

Persons at Risk

Residents / Occupants of 32 flats,
 Visitors,
 Sandwell MBC employees,
 Contractors,
 Service providers (e.g. meter readers, delivery people etc)
 Statutory bodies (e.g. W.M.F.S, Police, and Ambulance.




Section 5


Building Plan

A typical floor layout showing horizontal lines of compartmentation, lift shafts, dry riser installation and AOVs etc.


The plans have been shared with WMFS electronically via their portal.

Ground floor

-  premise information box
-  main access point
-  dry riser




Floors 1-6




Floor 7



mechanical smoke extraction



Roof



Section 6

External envelope

Following the introduction of the Fire Safety Act 2021, consideration needs to be given to the external envelope of the building for any fire risk. This predominantly means the external wall construction including any insulation filler. It also includes balconies and any other fixtures as well as doors and windows.

Details of the external wall construction have been provided to the fire service via the WMFS portal in line with fire safety regulations 2022

With regard to the external façade, the materials, construction, and their constituent properties have been taken from a database provided by Sandwell Metropolitan Borough Council. A third party approved contractor has been appointed to carry out External Wall Assessments of Sandwell Metropolitan Borough Councils Higher Risk Buildings.

A breakdown of the materials used and whether these or their combination or application present an acceptable level of fire risk has been recorded below.

- 1) The front and rear elevations are traditional masonry.



- 2) The side elevations were clad with a Wetherby mineral wool, silicon render system, fire classification A2 during a 2009 refurbishment.



- 3) Each flat within the block has access to an individual balcony. These are cantilevered concrete with a steel and glass balustrade. There was no evidence of screening on balconies at the time of the assessment.



- 4) Communal windows are single glazed units housed in powder coated aluminium frames.



- 5) Flat windows are double glazed units housed in timber frames with an external powder coated aluminium face.



- 6) The front and rear entrances to the building have powder coated aluminium doors.



Section

7

Means of Escape from Fire

- 1) The site has 2 protected staircases that provide a sufficient means of escape. Each staircase in width is 986mm from handrail to wall.



- 2) All corridors are of adequate width (at least 1050mm) and will be maintained clear to that width as a minimum.
- 3) None of the corridors that form part of the means of escape are dead ends.
- 4) The means of escape are protected to prevent the spread of fire and smoke.
- 5) The communal landing / staircases are protected by use of notional & nominal self-closing 44mm 30-minute timber fire doors with vision panels. All doors have been upgraded with intumescent strips / cold smoke seals.




- 6) All communal doors are fitted with automatic closing devices that are checked on a regular basis by Caretaking Teams as part of their checks. Defective closing devices are replaced either by the Caretaking Team(s) or the in-house repairs team(s).

- 7) All communal fire doors are subject to a 12-week check by the Fire Safety Rapid Response Team.
- 8) The final exit doors have door entry systems installed. These systems are designed to fail safe i.e. door unlocked in the event of a power failure. This prevents residents being locked in or out of the building.



- 9) Automatic smoke ventilation is employed to the head of the rear staircase. This is tested, inspected, and maintained by a competent procured contractor in accordance with BS7346. The frequency for the maintenance checks are twice per year (April and October) of each calendar year.



- 10) There is a master reset switch located on the 7th floor rear staircase landing. The switch is operated by a key which can be found in the firefighter's white box.



- 11) The waste disposal chutes are located on each landing to the front staircase. Hoppers are 1.5-hour fire rated to BS 476 part 8.



- 12) Communal windows are lockable however, windows were unlocked and open at the time of the assessment.



- 13) Communal areas are kept free of flammable items. The communal areas are checked on a regular basis by Caretaking / Cleaning teams 365 days per year and all items of rubbish are immediately removed. There is also an out of hour's service that allows combustible items of furniture / rubbish to be removed.


- 14) Individual floor mats were noted outside some flats. Fire rating of these mats is unknown but deemed to be of low risk.



- 15) Emergency lighting is provided to communal lobbies and stairs. Checks are done on a monthly basis by Sandwell MBC in house electrical team or approved contractor.



- 16) Dry riser inlet / outlets on lobbies are housed in cupboards with FD30s doors and secured by suited 54 key mortice locks. All outlet valves are secured in the closed position by cable tie.



- 17) Service cupboards are 44mm nominal fire doors with intumescent strips and cold smoke seals, secured with type 138 suited mortice locks to allow residents access to their electricity meters.



- 18) The surface coatings to the communal areas are Class 0 rated.
- 19) The building has sufficient passive controls that provide effective compartmentation in order to support a Stay Put-Unless Policy. Therefore, residents are advised to remain in their flat unless the fire directly affects them, or they are asked to leave by the emergency services.
-

- 20) Individual flat doors are FD30s composite doors with the majority being manufactured by Permadoor, generally, these are in good condition. Flat 106 has an FD30s manufactured by Nationwide and flat 122 has an FD30s manufactured by IG Doors.



- 21) **The front entrance door to Flat 115 had been temporary repaired, this was noted in the previous FRA but to date this has not been repaired. This flat entrance door should be replaced as soon as practicable with a certified FD30s.**



- 22) Access was gained to sample flat entrance doors of properties; this was to establish that doors had not been tampered with by residents etc.

- a) Flat 116 – Entrance door is correct.



b) Flat 118 – Entrance door is correct.



c) Flat 119 - Entrance door is correct.



23) Most trunking for power cables in communal areas is of metal construction and contain intumescent pads or pillows.



24) However, a small amount of plastic trunking was visible, it is understood that this trunking provides telecommunications cables for flats.



Section

8

Fire Detection and Alarm Systems

- 1) Early warning is limited to hard wire or battery smoke alarms within each of the resident's flats. The equipment is subjected to a cyclical test.

- 2) Based on the sample of properties accessed during the current and previous fire risk assessment, smoke alarms within resident's flats are installed to a combination of LD2 & LD3 standard. Despite best endeavours only three properties provided a response during this fire risk assessment.

Flat 116 – LD3 Hallway only.

Flat 118 – LD3 Hallway only.

Flat 119 – LD3 Hallway only.

- 3) *Based on samples taken from the previous fire risk assessment in September 2023, and information kept on file, (JM) smoke alarms within resident's flats are installed to a combination of an LD2 & LD3 Standard.*

LD1 all rooms except wet rooms

LD2 all-risk rooms e.g. Living Room, Kitchens, and Hallway.

LD3 Hallway only

- 4) There is no effective means for detecting an outbreak of fire to communal areas. The reason for this are:
 - I. Such systems may get vandalised.
 - II. False alarms would occur.
 - III. A Stay Put - Unless policy is in place

- 5) A sprinkler or deluge system is provided to the refuse chute bin store. An approved contractor maintains the system. The frequency for the maintenance checks are twice per year (April and October) of each calendar year. The control panel for the system is located in the ground floor lobby service cupboard.




**Section
9**

Emergency Lighting

- 1) The premises has a sufficient emergency / escape lighting system in accordance with BS 5266 and has test points strategically located.
- 2) The self-contained units are provided to the communal landings, stairs, and lift motor room.



- 3) All installed equipment is checked and tested on a monthly basis by Sandwell MBC in house electrical team or approved contractor, in accordance with current standards.



Section 10

Compartmentation

- 1) The building is designed to provide as a minimum 1-hour vertical fire resistance and 1-hour horizontal fire resistance around flats stairwells and lift shafts. All doors are 30-minute fire resistant with cold smoke seals, including those in 1-hour rated walls.
- 2) The premise has sufficient compartmentation to limit the travel and effect of smoke and flame in event of a fire. Whilst the existing fire stopping is fit for purpose, there is a cyclical programme to ensure fire stopping has not been compromised by third parties and where applicable enhance the fire stopping.
- 3) All communal doors are fitted with automatic closing devices that are checked on a regular basis by Caretaking Teams as part of their checks. Defective closing devices are replaced either by the Caretaking Team(s) or the in-house repairs team(s).
- 4) All communal fire doors are subject to a 12-week check by the Fire Safety Rapid Response Team.
- 5) All service cupboards to communal landings are locked with suited 138 mortice locks. Residents have been provided with a key for access to their electricity metres.




- 6) A variety of methods / materials have been used to achieve fire-stopping including Rockwool, fire rated sponge and intumescent pillows.



- 7) The fire stopping / compartmentation is subject to a 12-week check by the Fire Safety Rapid Response Team.
- 8) Any remedial works arising from the fire stopping / compartmentation check(s) will be actioned immediately by the Fire Safety Rapid Response Team.
- 9) Access panels to stop taps are fixed to masonry and bedded on Intumescent material.



- 10) Individual flat doors are FD30s composite doors with the majority being manufactured by Permadoor. Flat 106 has an FD30s manufactured by Nationwide and flat 122 has an FD30s manufactured by IG Doors.



Refer to the door survey sheet below.

Farley Street 97-128 (O&E)	97-128 Farley Street;Tipton;West Midlands;;		
Farley Street 97-128 (O&E)	97 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	98 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	99 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	100 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	101 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	102 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	103 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	104 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	105 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	106 Farley Street;Tipton;West Midlands;;	Nationwide	Not glazed
Farley Street 97-128 (O&E)	107 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	108 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	109 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	110 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	111 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	112 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	113 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	114 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	115 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	116 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	117 Farley Street;Tipton;West Midlands;;	Permadoor	Partial glazing
Farley Street 97-128 (O&E)	118 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	119 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	120 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	121 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	122 Farley Street;Tipton;West Midlands;;	IG Doors	Not glazed
Farley Street 97-128 (O&E)	123 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	124 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	125 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	126 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	127 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed
Farley Street 97-128 (O&E)	128 Farley Street;Tipton;West Midlands;;	Permadoor	Not glazed

11) Flat 122 has a missing outer letterplate.



12) The access panel at the side of door 122 needs to be sealed with intumescent materials.



- 13) Flat number 125 has had a temporary repair to the front entrance door, this should be replaced at the earliest opportunity. Recorded in Section 7.



- 14) The communal landing & staircases are protected by use of notional self-closing 44mm 30-minute timber fire doors with vision panels.

It is recognised that these doors do not meet today's benchmark of a certified FD30s fire door install however, because they were installed at the time of the buildings construction and to the standard of that time they are deemed as acceptable so long as the doors are free of damage and function as they were intended to do so.

It has been recognised that all of the landing / staircase notional doors in this block have been upgraded with combined intumescent strips & cold smoke seals to enhance their original design and minimise departures from today's standards.



- 15) The hatch to the lift motor room is a 54mm 60-minute nominal fire door with combined intumescent strips & cold smoke seals.



- 16) 7th floor by flat 126 – Landing door warped towards head, requires replacement FD30s.



- 17) 7th floor by flat 128 – landing door warped and requires replacement FD30s. Outstanding from previous Fire risk Assessment.



Section 11

Fire Fighting Equipment

- 1) There is a fire hydrant adjacent the front main entrance.



- 2) The dry riser inlet is located in the ground floor lift lobby.



- 3) There is a dry riser outlet on each floor above to the right hand side of the lift car.



- 4) The dry riser is checked regularly as part of the Caretakers duties.
- 5) Maintenance contracts in place to service the valves twice per year (April and October) with a hydraulic test undertaken annually (October) to comply with the requirements of BS9990.

- 6) Portable fire extinguisher (CO2) is provided to the lift motor room. Maintenance contracts in place for maintenance of the extinguisher. The frequency for the maintenance checks are once (October) of each calendar year.



- 7) Bin room is protected by Deluge/sprinkler system and serviced 6-monthly. The control panel is in the ground floor lift lobby service cupboard.



Section 12

Fire Signage

- 1) All fire doors display “Fire Door Keep Shut” where appropriate.



- 2) Fire Action Notices are displayed throughout the building.



- 3) Yellow LPG warning signs are displayed within the lift cars.



- 4) Signage depicting the floor location of each flat is fitted to the ground floor lobby wall.



- 5) Floor indicator numbers are fitted to the wall of each floor on the communal staircase.



- 6) Signage depicting floor level and flat numbers are fitted to the wall of each floor lobby.



- 7) Generally, directional escape signage has been installed through most parts of the building. However, on the ground floor the exit signage was non-compliant. This signage has been updated by the assessor following the assessment.



Section 13

Employee & Resident Training/Provision of Information

- 1) All Caretaking / Cleaning Employees have undertaken fire safety training. This includes use of bespoke 'Fire Safety in High / Low Rise Flatted Accommodation' Video.
- 2) All employees are encouraged to complete 'In the line of fire' training on an annual basis.
- 3) Caretaking Teams are not currently trained in the effective use of fire extinguishers. The only extinguishers located are within the lift motor room. Caretaking Teams are not expected to tackle fires in this area.
- 4) Staff undertaking fire risk assessments are qualified to or working towards Level 4 Diploma in Fire Safety.
- 5) Fire safety information has been provided as part of tenancy pack.
- 6) Building safety and evacuation notices are displayed in common areas and lift cars.



- 7) Fire safety information has been provided as part of tenancy pack. Information regarding the Stay Put Unless fire evacuation strategy is provided to tenants.



- 8) Information regarding building safety is contained within a Building Safety Notice. This is affixed to the wall on the ground floor lift lobby of high rise blocks.

BUILDING SAFETY INFORMATION	 FARLEY STREET	FIRE SAFETY INFORMATION
<p style="text-align: center;"><u>TO KEEP YOU SAFE WE DO THIS</u> (green background)</p>	<p style="text-align: center;"><u>TO KEEP YOURSELF AND OTHERS SAFE, DO THIS</u> (blue background)</p>	<p style="text-align: center;"><u>SAVE LIVES, DON'T DO THIS</u> (red background)</p>
Mains electrical system is tested every 5 years	<p style="text-align: center;">FIRE ALARMS DO NOT CONNECT TO THE FIRE SERVICE. IN AN EMERGENCY DIAL 999 OR 112 AND ASK FOR POLICE, AMBULANCE OR FIRE SERVICE</p>	Fire Risk Assessments (FRAs) are undertaken in line with the Regulatory Reform (Fire Safety) Order 2005
Gas supply tested annually		Stairs and corridors are escape routes and must be kept clear
Water supplies checked in line with water hygiene regulations		Emergency lighting comes on in the event of power failure and is checked monthly
There is 4 yearly check of the structural condition		Walls, floors and ceilings around flats provide a minimum of 60 minutes fire resistance
An asbestos survey has been completed and available on request		Flat doors are fire rated to protect the escape route. DO NOT REMOVE THE DOOR CLOSERS
This building has protection against lightning strikes. The system is checked annually		Smoke and heat detector/alarms are in resident's flats only
There is a "dry riser" to assist fire-fighters in getting water to a floor level. This is checked 6 monthly.		Smoke detectors in communal areas are to open automatic vents and not to raise the alarm.
The external façade is brick and Wetherby mineral wool insulated render (Fire Classification A2).		<p style="text-align: center;">THIS BUILDING IS DESIGNED TO SUPPORT A <i>STAY PUT</i> POLICY. IN THE EVENT OF A FIRE ELSEWHERE, STAY IN YOUR FLAT <i>UNLESS</i> AFFECTED BY FIRE OR SMOKE.</p>
Fire safety advice	<p>Further information available at www.Sandwell.gov.uk your My Sandwell account or the Fire Safety Liaison Officer on 0121 569 6000 lee_millican@sandwell.gov.uk Abdulmonim_Khan@sandwell.gov.uk</p>	Sandwell FRAs

Section

14

Sources of Ignition

- 1) Smoking is prohibited within any communal parts of the building in line with Smoke Free England legislation.
- 2) Hot working is not normally conducted. If essential maintenance requires the use of hot work processes, then corporate policies and procedures are to be followed.
- 3) Portable electrical equipment used as part of the Caretaking / Cleaning regime is subject to annual PAT Testing. This information is held by the Estate Services Manager Bryan Low.
- 4) The fixed electrical installation shall be tested every 5 years. The date of the most recent inspection is 19th October 2023 where the install was deemed as satisfactory, but some minor improvements recommended.
- 5) Electrical installations and dry risers are contained within dedicated service cupboards that are secure and protected by means of nominal 44mm timber fire doors with intumescent strip & cold smoke seals.
- 6) There is lightning protection installed to the block. Maintenance contracts are in place for lightning conductor testing in accordance with BS 6651.



- 7) The purpose of an external lightning protection system is to intercept, conduct and disperse a lightning strike safely to earth. Earth pads were noted in several locations at the base of the building.


- 8) Portable heaters are not allowed in any common parts of the premises.
- 9) Gas appliances and pipework (where installed) are subject to annual testing and certification. This cyclical contract is managed by the in-house Gas Team. Gas supply pipework is internal to the building.



**Section
15**

Waste Control

- 1) There is a regular Cleaning Service to the premises.



- 2) Refuse containers are located in the bin store which is to the right-hand side of the main entrance. Access is via a motorised roller shutter; key is stored in the firefighter's white box. All refuse containers are emptied regularly.



- 3) Regular checks by Caretakers minimise risk of waste accumulation.
 - 4) 'Out of Hours' service in place to remove bulk items.
-

**Section
16**

Control and Supervision of Contractors and Visitors

- 1) Responsive Repairs service delivered by Sandwell MBC necessitates the production of an order via the computerised repairs system. Details of any known risks are documented on the repair order.
 - 2) Hot works are not permitted unless authorisation is given via the approved officer. The hot works procedure is to be followed.
 - 3) Utility companies are not allowed to access any service cupboard or secure area. They must request and collect maintenance keys from the Investments office @ Roway Lane. This allows scrutiny of what is the scope of any works such as installation of tenant's broadband / phone line etc.
 - 4) Where contractors are appointed to undertake major refurbishment works, Sandwell MBC Urban Design team will put control measures in place. Such Measures include: -
 - a) Pre-Contract Meetings – where contractor is made aware of all working arrangements and safe systems of work to be adopted. Issues covered in this meeting will include:
 - Health and Safety.
 - Site security.
 - Safety of working and impact on children/school business.
 - Fire risk, if any.
 - Site Emergency Plan.
 - b) Monthly Site Meetings – in order to monitor, review and share any new information including any new risks.
 - c) Site monitored daily whilst work is in progress by Clerk of Works / Health and Safety Officers.
 - d) Final Contractor review on completion of works undertaken.
-

**Section
17**

Arson Prevention

- 1) Regular checks are undertaken by Caretakers / Cleaning Team(s) 365 days per year which helps reduce the risk of arson.
- 2) Restricted access to the premises by means of a door entry system.



- 3) The perimeter of the premises is well illuminated.



- 4) Since the previous fire risk assessment there has not been any reported fire incidents that have required an emergency response.
-

Section 18

Storage Arrangements

- 1) Residents instructed not to bring L.P.G cylinders into block.



- 2) The tenancy conditions, Section 7 – Condition 5.6 stipulates “If you live in a flat or maisonette, you, people living with you and any visitors to your property must not keep or use paraffin oil, petrol, bottled gas appliances or any other explosive, FLAMMABLE, or dangerous material in the property. This restriction also applies to any storage facility situated in or attached to the block, which has been provided for your use.”
 - 3) No Flammable liquids stored on site by Caretakers / cleaners.
 - 4) All store cupboards are kept locked.
 - 5) There are no flammable liquids or gas cylinders stored on site.
-

**Section
19**

**Additional Control Measures.
Fire Risk Assessment - Action Plan**

Significant Findings

Action Plan

It is considered that the following recommendations should be implemented to reduce fire risk to, or maintain it at, the following level:

Trivial Tolerable

Definition of priorities (where applicable):

P1 Arrange and complete as urgent – Within 10 days

P2 Arrange and complete within 1-3 Months of assessment date

P3 Arrange and complete within 3-6 Months of assessment date

P4 Arrange and complete exceeding 6 months under programmed work



Fire Risk Assessment Action Plan




Name of Premises or Location:

197 – 128 Farley Street

Date of Action Plan:




24/09/2024

Review Date:




Question/ Ref No	Required Action	Supporting photograph	Priority	Timescale and Person Responsible	Date Completed
7/21	Replace flat entrance door. This action has been outstanding since the previous FRA.		P2	Within 1-3 months. Repairs	



Fire Risk Assessment

10/11	Replace missing outer letterplate for Flat 122		P2	Within 1-3 months. Fire Rapid Response	
10/12	Fire stop access panel outside Flat 122 using appropriate fire resistant materials.		P2	Within 1-3 months. Fire Rapid Response	
10/16	7 th floor by flat 126 – Landing door warped towards head, requires replacement FD30s.		P4 Outstanding from previous Fire risk Assessment.	Exceeding 6 months Repairs Emailed Ian Sorrell	

Fire Risk Assessment

10/17	7 th floor by flat 128 – landing door warped and requires replacement FD30s.		P4 Outstanding from previous Fire risk Assessment.	Exceeding 6 months Repairs Emailed Ian Sorrell	
12/17	Replace non-compliant exit signage on the ground floor. Replace with	 	This action has been resolved following the FRA.		

Fire Risk Assessment



When undertaking future improvement program(s), it is advised that the observations listed below should be given consideration (noting that the safety of the residents is not jeopardised by these, and all steps to reduce any known risks have been taken).

Observations

Some notional communal landing doors show signs of wear and tear due to age. Consideration should be given to upgrade with certified FD30s door sets & combination frames.



Signed

 Adrian Jones	Fire Risk Assessor	Date: 24/09/2024
	Quality Assurance Check	Date: 26/09/2024



Significant Hazards on Site and Information to be Provided for the Fire Service




Name of property: 1-32 Horton St, Tipton.

Updated: 23/06/2024

Premise Manager: Tony Thompson

Tel. No.: 0121 569 2975

Hazard	Information/Comments
PEEPS	Referral generated for flat 15 Refer to Secure Premise Information Box
Asbestos	An asbestos survey has been undertaken of the communal areas. Survey held by Sandwell Housing (Derek Still Tel:- 0121 569 5077). <i>Include survey</i>

Asbestos Survey		Property Address	1-32 Horton Street, Great Bridge, Tipton, DY4 7JW.		Office use <input checked="" type="checkbox"/>			
Surveyed by	W Colbourne	Date	26/02/2014		Checked by	DEREK STILL	Desktop Check	Site Check
Reason for request		HSG 264 - Survey Report Type		Date	31/03/2014			
Investment Void		Refurbishment Survey		HIGH RISE 7 STOREY				
Investment Tenanted		Management Survey				<input checked="" type="checkbox"/>		
R & M Void		SHAPE Interrogated.				<input checked="" type="checkbox"/>		
R & M Tenanted		No Existing SHAPE Data.						
Medical / Emergency - Heating Works		Existing SHAPE Data.				<input checked="" type="checkbox"/>		
Communal Areas	<input checked="" type="checkbox"/>	Refurb Surveys Interrogated ?						
						Year Built	1946	
				Notes / including details of similar property surveys completed. Revised By G.Carrington – 23/06/2022				
Building Surveyors 0121 569 5077				Asset Team – Investment Division Operations & Development Centre Roway Lane Oldbury B69 3ES				
								

Fire Risk Assessment

Sample Locations	Property Address	1-32 Horton Street, Great Bridge, Tipton, DY4 7JW.						
LOCATION	MATERIAL	QTY	SURFACE TREATMENT	SAMPLE REF	RESULT	HSE NOTIFY	Labelled	ACTION TAKEN ON CONTRACT
IF DURING THE COURSE OF WORK SUSPECTED ACM'S ARE IDENTIFIED THAT ARE NOT CONTAINED WITHIN THIS REPORT STOP WORK & SEEK ADVICE								
FLOORS 1-7 WALLS	TEXTURED COAT	100m ² +	SEALED	BB3338	NONASBESTOS	NO	NO	
FLOORS 1-7 CEILING	TEXTURED COAT	100m ² +	SEALED	BB3338	NONASBESTOS	NO	NO	
GROUND FLOOR WALLS	TEXTURED COAT	60m ²	SEALED	BB3338	NONASBESTOS	NO	NO	
LIFT MOTOR ROOM	NO ACM'S FOUND							
ALL BALCONIES – RAIN WATER PIPE	CEMENT	-	SEALED	PRESUMED	CHRYSOITILE	NO	-	-
FLAT ROOF MINERAL FELT TO LIFT MOTOR-FRONT AND REAR ENTRANCES	BITUMINOUS	-	-	-	-	-	-	REQUEST SAMPLE IF TO BE DISTURBED
ITEMS SHOWN BELOW HAVE BEEN ASSESSED ON SITE BY THE ASBESTOS SURVEYOR & ARE CONFIRMED NOT TO BE ACM'S.								
LOCATION DESCRIPTION	MATERIAL	LOCATION DESCRIPTION	MATERIAL	LOCATION DESCRIPTION	MATERIAL			
LIFT MOTOR ROOM CEILING	PLASTERBOARD							
FLOOR 7 DRY RISER CEILING	PLASTERBOARD							
ALL LANDING DUCT COVERS UNLESS STATED ABOVE	SUPALLIX PLYWOOD							
GROUND FLOOR TRANSOM PANEL OVER INNER DOOR	SUPALLIX PLYWOOD							
GROUND FLOOR HIGH LEVEL BOXING TO TRUNKING NEXT TO FRONT ENTRANCE DOOR	SUPALLIX							

About the Report

All Survey Methodology is based upon HSE document HSG 264 - Asbestos: The Survey Guide. All surveyors are experienced British Occupational Hygiene Society (BOHS) P402 qualified surveyors with extensive Surveying & Refurbishment Project experience specific to Sandwell Homes' managed housing stock.

The person or persons using this report to programme refurbishment work on site are assumed to be competent & experienced in the field of domestic refurbishment projects & have suitable & sufficient asbestos awareness to understand the scope of this report & apply it to the project. All trade operatives working on site are also expected to have relevant asbestos awareness training & experience. IF IN DOUBT STOP & ASK!

SHAPE: Sandwell Homes' integrated ICT solution holds the Company Asbestos Register. The Asbestos Register is interrogated when completing the asbestos survey report to ensure that ACM's in similar properties are considered where relevant. The Register holds details of all suspected or confirmed ACM's identified during Refurbishment & Demolition programmes as well as Repairs activities for the past 11 years. If potential ACM's have been identified within difficult to survey areas such as Cavity Walls, Floor Voids etc these will be highlighted within the report. The interrogation of the Company Asbestos Register complements the survey & report process it does not substitute the Refurbishment & Demolition Survey.

Void Properties – The Building Surveying team who undertake Refurbishment & Demolition Asbestos Surveys also undertake Domestic Energy Assessment Surveys, ~~Borescope~~ Surveys for Thermal Insulation & Fire Integrity Assessments to a representative percentage of the void turn over.

Site Overview Page 2 – This section is included to aid surveying & to ensure comprehensive survey information is detailed.

Term	Explanation
Property Address	Specific Property to which survey relates.
Surveyed by	Relates to P402 trained surveyor.
Blank	Blank
Type of Work to be undertaken	Relates to the envisaged type of work that the Asbestos Survey Report will be used to aid. This assists the asbestos surveyor to guide his survey methodology & will help the users of this report decide if it is suitable for the work activity being undertaken.
ACM	Asbestos Containing Material.
HSE Notify	This highlights if a material normally requires notification to the Health & Safety Executive prior to removal. GUIDANCE ONLY.
Bulk Sample	Sample of potential ACM that is representative of the whole.
Request Sample	The item described has not been tested for Asbestos content. The item must be presumed to contain asbestos until sampling confirms. If work is going to be undertaken in this area sample should be requested prior to work starting.
Awaiting Results	If no results have been detailed then you must not work on these items until you receive further confirmation.
Extent	An estimate of quantity will be given where possible to aid work planning & valuation.
Labels	Materials will be labelled where practical. Labelling will be not be undertaken on low risk materials e.g. floor tiles, Textured Coatings etc or where labelling could easily be removed or would cause potential exposure if removed. All presumed ACM's will be labelled as "Asbestos" where possible. All sampled materials will be labelled with an "Asbestos Sampled" label.

Term	Explanation
Photo's	These will usually be provided for the front elevation of the property to aid identification.
Sampled by	P402 trained surveyor.
Checked by	P402 trained surveyor who checks report prior to issuing.
Survey Report Type	Report type is determined by the type of work to be undertaken. The reader of this report must satisfy themselves that the scope of the survey is sufficient for the purpose of work being undertaken.
Refurbishment Survey	HSG 264 – Refurbishment & Demolition Survey. Surveying undertaken to all parts of the property presuming full decent homes refurbishment, which may include: New Kitchen, New Bathroom, Electrical Rewire, Re-roof, Full Heating System. Taking account of the complete structure of the property & archetypal information available. This survey has been carried out without detailed knowledge of the works to be undertaken during refurbishment.
Management Survey	A management survey is the standard survey. Its purpose is to locate, as far as reasonably practicable, the presence and extent of any suspect ACM's in the building which could be damaged or disturbed during normal occupancy, including foreseeable maintenance and installation, and to assess their condition.
Cavity Walls / Floor Voids or similar.	Will be assessed at survey stage & desktop assessment of similar archetypes.
SP	Strong Presumption that material contains asbestos. Used to qualify possible false negative laboratory results.
Photo's	Where practical & to aid the identification of ambiguous material locations photos will be included within the report to ensure that materials are identified on-site correctly. Photos will be annotated where necessary.