Fire Risk Assessment

Martley Road 36-46,48-58





Martley Road, Oldbury, B69 1DZ

Date Completed: 15/08/2022

Officer: L. Conway Trainee Fire Risk Assessor

Checked By: Tony Thompson **Fire Safety Manager**

Current Risk Rating 0 = Low



Subsequent reviews

Review date	Officer	Comments

Contents

Section 0	Introduction	
Section 1	Significant Findings (executive summary)	
Section 2	People at Significant Risk of Fire	
Section 3	Contact Details	
Section 4	Description of Premises	
Section 5	Building Plan	
Section 6	External Envelope	
Section 7	Means of Escape from Fire	
Section 8	Fire Detection and Alarm Systems	
Section 9	Emergency Lighting	
Section 10	Compartmentation	
Section 11	Fire Fighting Equipment	
Section 12	Fire Signage	
Section 13	Employee Training	
Section 14	Sources of Ignition	
Section 15	Waste Control	
Section 16	Control and Supervision of Contractors and Visitors	
Section 17	Arson Prevention	
Section 18	Storage Arrangements	
Section 19	Additional Control Measures; Fire Risk Assessment – Level 2 Action Plan	
Appendix 1	Significant Hazards on Site and Information to be provided for the Fire Service	

U

Introduction

The Regulatory Reform (Fire Safety) Order 2005 (RR(FS)O) places a legal duty on landlords to complete a fire risk assessment (FRA). Specifically, RR(FS)O article 9. — (1) "The responsible person must make a suitable and sufficient assessment of the risks to which relevant persons are exposed for the purpose of identifying the general fire precautions he needs to take to comply with the requirements and prohibitions imposed on him by or under this Order".

This fire risk assessment has been written to comply fully with the above legislation which is enforced locally by West Midlands Fire Service. If required, complaints can be made to them by telephone on 0121 380 7500 or electronically on https://www.sanet/our-services/fire-safety/#reportfiresafety. In the first instance however, we would be grateful if you could contact us directly via https://www.sandwell.gov.uk/info/200195/contact_the_council/283/feedback_and_complaints or by phone on 0121 569 6000.


The date of the fire risk assessment is on the front page, followed by any subsequent reviews. A recurring time frame is not set in legislation. The council has procedures and policies in place that will trigger a review of the fire risk assessment. This then is recorded on the fire risk assessment is not currently suitable and sufficient, then a new fire risk assessment will be undertaken and become the current fire risk assessment. The previous fire risk assessment will be retained in the building safety case for that building.

The following diagrams illustrate those procedures and persons that support the effective planning, organisation, control, monitoring and review of the preventive and protective measures. This information is provided as required under the RR(FS)O.



The above processes and procedures are overseen by the Fire Safety, Facilities and Premises Manager who reports to the Business Manager - Surveying and Fire Safety.

These managers attend the Fire Safety Core Group for scrutiny which is part of the governance structure below.



To summarise the fire risk assessment, in this scenario the RR(FS)O requires the prescribed information to be recorded. The prescribed information is the significant findings of the fire risk assessment and those groups or persons especially at risk from fire. This is recorded here in <u>section 1</u>. Also required to be recorded under article 11, are the fire safety arrangements for the planning, organisation, control, monitoring and review of the preventative and protective measures. The information shown above is part of this requirement.

1

Significant findings

The significant findings (executive summary) of the fire risk assessment include those measures that have been or will be undertaken by the responsible person in order to comply with the RR(FS)O 2005. Groups of people especially at risk of fire include such people as remote or lone workers, at risk due to layout of the building, visitors and contractors unfamiliar with the building layout as well as those with physical, sensory or mental health issues.

A third requirement that under the order must be recorded is the fire safety arrangements. This is the effective planning, organisation, control, monitoring and review of the preventive and protective measures. These are shown in the introduction.

Significant findings

Include a brief summary of protective and preventative measures where relevant along with any issues found;

The escape strategy is 'Stay Put Unless'. This means in the event of a fire in your flat you should evacuate. If there is a fire elsewhere in the building you should stay put unless you are affected by fire or smoke

Section number	Section Area	Individual Risk Level
Section 6	External Envelope The blocks are of cavity wall construction with a pitched roof. Both properties are Adjoined with separate entrances for each and have UPVC double glazed windows installed.	0
Section 7	Means of Escape from Fire Each block has a single staircase that provides a sufficient means of escape. Decorative plastic plants, pushchair and other combustible items stored in communal areas to be removed.	2

Section 8	Fire Detection and Alarm Systems Individual flats are fitted with hardwired smoke detection to an LD3 standard in both blocks of flats from samples taken.	
Section 9	Emergency Lighting The premises do not appear to have any emergency / escapes lighting system in accordance with BS 5266. This is required due to the staircase. However, lighting is present.	0
Section 10	Compartmentation individual flat entrance doors to both blocks are FD30s rated fire doors. Fire stopping required in common roof space around penetrations and underside of roof.	0
Section 11	Fire Fighting Equipment The premises have no provision for firefighting equipment.	0
Section 12	Fire Signage Fire door keep shut and no smoking signs have been installed.	0
Section 13	Employee Training All staff receive basic fire safety awareness training.	0
Section 14	Sources of Ignition The fixed electrical installation was last inspected 25/01/2019.	0
Section 15	Waste Control Caretakers undertake regular checks of the building. Bins are emptied frequently and stored away from the premises.	0

Section 16	Control and Supervision of Contractors and Visitors Contractors are controlled centrally, and hot works permits are required where necessary.	0
Section 17	Arson Prevention There is external lighting and a door entry system which prevents unauthorised access.	0
Section 18	Storage Arrangements Residents are instructed not to bring LPG cylinders into the building. Residents have access to storage cupboards in the communal areas adjacent to there flats.	0

Risk Categories			
Risk Rating	Description		
5	Presents a serious risk to life safety. This matter requires immediate action and must be given a high priority.		
4	A significant safety issue.		
3	A safety issue, but where the level of risk is reduced by a combination of compensatory factors; or where there is a risk to property only.		
2	A desirable improvement to increase protection from fire.		
1	A minor improvement to safety.		
0	No risks identified		

The highest risk rating selected shall be transferred to the front page of the risk assessment using a RAG rating as follows

Current Risk Rating 4-5 = HIGH

Current Risk Rating 1-3 = MEDIUM

Current Risk Rating 0 = Low

2

People at Significant Risk of Fire

Persons at significant risk of fire does not just refer to those people with physical, sensory or mental health issues. It also includes those at risk due to the layout or features of the building such as inner rooms or dead-end conditions. Persons may also be at risk due to remote or lone working.

The RR(FS)O requires that these people are identified in any fire risk assessment.

Sandwell Council is currently writing a policy and procedures for Personal Emergency Evacuation Plans (PEEPs). This is based on tenants identifying themselves as requiring a PEEP. This will be reliant on the outcomes of the government consultation which is yet to be published.

Where this is known and PEEPs have been completed, it will be captured in this fire risk assessment along with any building layout or working practices placing people at significant risk of fire.

3

Contact Details

The Chief Executive of Sandwell Metropolitan Borough Council has ultimate responsibility for the site as the responsible person identified by the RR(FS)O 2005.

The Chief Executive has put a structure in place to support the management of the site.

This includes the role of Building Safety Manager who has duties as defined within the Regulatory Reform (Fire Safety) Order 2005.

The contact names to support the management of the site are as follows:

Chief Executive

Kim Bromley Derry (Interim Director)

Director of Housing

Gillian Douglas

Business Manager Surveying and Fire Safety (Building Safety Manager)

Phil Deery

Fire Safety, Facilities and Premises Manager

Tony Thompson

Team Lead Fire Safety and Facilities

Jason Blewitt

Fire Risk Assessor(s)

Pardeep Raw

Carl Hill

Louis Conway (trainee)

Resident Engagement Officer - Fire Safety

Lee Mlilo

Neighbourhood Office Manager

Rachel Price

Please note, the above details are correct at the time of the production of the risk assessment and may be subject to change

Description of Premises

Martley Road 36-46,48-58 Martley Road Oldbury B69 1DZ

Description of the Property

The low-rise blocks were constructed in 1961.





The blocks consist of 2 storeys (inclusive of the ground floor). Each of the floors contains 3 number dwellings. Both blocks are adjoined however access into each building is separate.

The blocks have a main entrance/exit to the front elevation and a further entrance/exit located on the rear elevation. Both front and rear entrances have a door entry system with a fob reader installed. The front entrance only, has a firefighter override by use of a drop latch key.







(48-58)







(36-46)

The blocks are of cavity wall construction with a pitched roof. Access to the roof space is by loft hatch which is padlocked. Keys are held with the local housing team.

The communal, any workplace areas and the external envelope of the building are subject to the Regulatory Reform (Fire Safety) Order 2005 as confirmed by the Fire Safety Act 2021.

The enforcing authority is West Midlands Fire Service.

The emerging adments to week mid	and in o convice.
High/Low Rise	Low Rise
Number of Floors	2
Date of Construction	1961
Construction Type	Traditional Brick
Last Refurbished	Unknown
External Cladding	None
Number of Lifts	None
Number of Staircases	One (per block)
Automatic Smoke Ventilation to	None
communal area	
Fire Alarm System	None
Refuse Chute	None
Access to Roof	Loft Hatch (Padlocked)
Equipment on roof (e.g. mobile	None
phone station etc)	

Persons at Risk

Residents / Occupants of 6 flats (per building)

Visitors,

Sandwell MBC employees,


Contractors,

Service providers (e.g. meter readers, delivery people etc)

Statutory bodies (e.g. W.M.F.S, Police, and Ambulance)

Building Plan

A general plan that shows the location of the building.



External envelope

Following the introduction of the Fire Safety Act 2021, consideration needs to be given to the external envelope of the building for any fire risk. This predominantly means the external wall construction including any insulation filler. It also includes balconies and any other fixtures as well as doors and windows.

Provide a breakdown of the materials used and whether these or their combination or application present an acceptable level of fire risk.

1) The blocks are of cavity wall construction with a pitched roof. Both properties are Adjoined with separate entrances for each block of flats.





2) The windows to both blocks of flats are UPVC double glazed units including the central communal areas.



3) It had been noted that the column supporting the canopy above the main entrance to block 48-58 was loose



7

Means of Escape from Fire

- 1) The site has a single staircase for each block that provides a means of escape
- 2) All corridors are of adequate width (at least 1050mm) and will be maintained clear to that width as a minimum.
- 3) None of the corridors that form part of the means of escape are dead ends.
- 4) The means of escape are protected to prevent the spread of fire and smoke.
- 5) The only communal doors within the blocks are the final exit doors which are fitted with automatic closing devices that are checked on a regular basis by Caretaking Teams as part of their checks.

 Defective closing devices are replaced either by the Caretaking Team(s) or the in-house repairs team(s).
- 6) The final exit doors have door entry systems installed. These systems are designed to fail safe i.e. door unlocked in the event of a power failure. This prevents residents being locked in or out of the building.
- 7) Communal windows can only be opened without the use of a key.
- 8) Communal areas are kept free of flammable items. The communal areas are checked on a regular basis by Caretaking / Cleaning teams 365 days per year and all items of rubbish are immediately removed. There is also an out of hour's service that allows combustible items of furniture / rubbish to be removed. (image on next page).





- Lighting is provided in the communal landing and stairwell however this is not emergency lighting.
- 10) Electric meter cupboard doors are FD30 rated, secured with a Budget lock. Residents have been provided with a key for access to their electricity meters
- 11) The surface coatings to the communal areas are Class 0 rated. (ceiling)
- 12) The building has sufficient passive controls that provide effective compartmentation to support a Stay Put-Unless Policy. Therefore, residents are advised to remain in their flat unless the fire directly affects them.
- 13) Individual flat doors are FD30s rated composite doors sets
- 14)Access is gained to a sample of properties as part of the fire risk assessment to ensure the doors have not been tampered with by residents etc

Flat 48-58.

Access was granted to flat 48 and the door had no evidence of being tampered with.

Flat 36-46,

Access was gained to flats 40 and 44 and there was no evidence of tampering.

15) Outside flat no 50 has bib tap fitted on communal area covered by timber box. (this has been installed by Caretaking Teams to facilitate cleansing of the block(s)



16) Child seat left in communal hallway underneath the stairway in block 48-58.



17) variety of plastic flower decorations placed on floor and hung on wall outside flat 48.





18) pushchair/ bike and other items left outside flat 56 as well as a wicker hanging basket with plastic decoration to be removed to keep the means of escape sterile. (image on next page)





- 19) It was noted in the previous risk assessment that Individual dwelling store cupboards adjacent to individual front doors have non fire rated doors. This has been added to a future upgrade plan.
- 20) It was noted that the walls adjacent flat 48 had been painted. The fire rating of this is unknown. It was also noted that lamented flooring had been placed on the floor outside flat 48.
- 21) Flats 36, 38, 40, 44, 48, 50, 54, 56, and 58 had door mats outside the entrances to there flats the fire rating of these are unknown.

Good housekeeping is fundamental to reducing risk in blocks of flats. Controlling the presence of combustible materials and ignition sources not only reduces the potential for accidental fires to start and develop in the common parts, it also significantly reduces the scope for deliberate fires. It also ensures escape routes are free of obstructions that might hinder the evacuation of people from the building and access for firefighters

Fire Detection and Alarm Systems

- 1) Early warning is limited to hard wire or battery smoke alarms within each of the resident's flats the equipment is subjected to a cyclical test.
- 2) Based on the sample of properties accessed during the fire risk assessment the smoke alarms within resident's flats are installed to an LD3 Standard.

(Flats 36-46)

Flat 40 – LD3, 1x smoke detector in hallway

Flat 44 – LD3 1x smoke detector in hall and lounge

(Flats 48-58)

Flat 48 – LD3 1x smoke detector in hallway

For information

LD1 all rooms except wet rooms

LD2 all-risk rooms e.g. Living Room, Kitchens and Hallway.

LD3 Hallway only

- 3) There is no effective means for detecting an outbreak of fire to communal areas. The reason for this are:
 - I. Such systems may get vandalised.
 - II. False alarms would occur.
 - III. A Stay Put Unless policy is in place

9

Emergency Lighting

1) The premises do not appear to have any emergency / escapes lighting system in accordance with BS 5266. This is required due to the staircase. However lighting is present.



2) As there is no emergency lighting there are no test being conducted in this current moment in time.

Compartmentation

This section should be read in conjunction with Section 4

- 1) Both buildings are designed to provide as a minimum 1-hour vertical fire resistance and 30 minutes horizontal fire resistance. This is not possible in communal areas due to open plan staircase.
- 2) The premise does not have sufficient compartmentation to limit the travel and effect of smoke and flame in event of a fire in communal areas due to open plan staircase.
- 3) All communal doors are fitted with automatic closing devices that are checked on a regular basis by Caretaking Teams as part of their checks. Defective closing devices are replaced either by the Caretaking Team(s) or the in-house repairs team(s).
- 4) All service cupboards to communal landings are lockable. Keys are held centrally unless containing resident's meters
- 5) The first-floor landing to both blocks contain a loft access that is secured with two padlocks. (loft hatch from both blocks)





6) Access was gained to common loft space in block 48-58. Compartmentation in the loft space is inadequate as there are penetrations that have not been sealed and gaps between the wall and roof. At the time of the visit it was not possible Access block 36-46 loft space.




7) Flats 50, 56, 36 and 42 all have bathroom windows onto the communal landing with obscured glazed units fitted that are a mixture of UPVC and timber construction. Flat 50 has the addition of an extractor fan fitted through the glass.




8) A variety of methods / materials have been used to achieve firestopping including Rockwool and intumescent pillows. Whilst the existing fire stopping is fit for purpose, there is a cyclical programme to ensure fire stopping as not been compromised by third parties and where applicable enhance the fire stopping.

5a) 36-46,



5b) 48-58,



9) Individual flat doors are FD30s rated composite fire door construction

Flats 48-58













Flats 36-46













10) It was noted that cracks along the sides of the 1st floor ceiling was present.

Section 11

Fire Fighting Equipment

1) The premise has no provisions for firefighting equipment.

Section 12

Fire Signage

1) "Fire Door Keep Shut" signs are displayed where appropriate.



2) No smoking signs are present throughout both blocks.



- 3) Fire Action Notices are not displayed throughout the building. (It was decided the signs are not necessary due to the building not having a complex layout as per Deputy Premise Manage.)
- 4) Yellow LPG warning signs are not displayed. (refer to section 15 point)

Employee & Resident Training/Provision of Information

- All Caretaking / Cleaning Employees have undertaken fire safety training. This includes use of bespoke 'Fire Safety in High / Low Rise Flatted Accommodation' Video.
- 2) All employees are encouraged to complete 'In the line of fire' training on an annual basis.
- 3) Caretaking Teams are not currently trained in the effective use of fire extinguishers.
- 4) Neighbourhood Directorate employees assigned to undertake Fire Safety Inspections have received IFE approved training via West Midlands Fire Service.
- 5) Fire safety has been provided as part of tenancy pack.

Sources of Ignition

- Smoking is prohibited within any communal parts of each building in line with Smoke Free England legislation.
- 2) Hot working is not normally carried out. If essential maintenance requires the use of hot work processes, then corporate policies and procedures are to be followed.
- 3) Portable electrical equipment used as part of the Caretaking / Cleaning regime is subject to annual PAT Testing. This information is held by the Estate Services Manager Bryan Low.
- 4) The fixed electrical installation shall be tested every 5 years. It was noted that the last inspection was 25/01/2019. This inspection certificate was only found in one of the blocks.



- 5) The electrical installation i.e. risers are contained within dedicated service cupboards that are secure and protected by means of a FD30S door.
- 6) Portable heaters are not allowed in any common parts of the premises.
- 7) Gas appliances and pipework (where installed) are subject to annual testing and certification. This cyclical contract is managed by the in-house Gas Team. Gas supply to the property is internal.
- 8) It was noted that a chiminea had been used in the rear yard (image on next page)



Waste Control

1) There is a regular Cleaning Service to the premises.



2) Refuse containers are emptied regularly and stored away from the premises enclosed by handrails.



- 3) Regular checks by Caretakers minimise risk of waste accumulation.
- 4) 'Out of Hours' service in place to remove bulk items.

Control and Supervision of Contractors and Visitors

- Responsive Repairs service delivered by Sandwell MBC necessitates the production of an order via the computerised repairs system. Details of any known risks are documented on the repair order.
- 2) Hot works are not permitted unless authorisation is given via the approved officer. The hot works procedure is to be followed.
- 3) Utility companies are not allowed to access any service cupboard or secure area. They must request and collect maintenance keys from the Investments office @ Roway Lane. This allows scrutiny of what is the scope of any works such as installation of tenant's broadband / phone line etc.
- 4) Where contractors are appointed to undertake major refurbishment works, Sandwell MBC Urban Design team will put control measures in place. Such Measures include: -
 - a) Pre-Contract Meetings where contractor is made aware of all working arrangements and safe systems of work to be adopted. Issues covered in this meeting will include:
 - Health and Safety.
 - Site security.
 - Safety of working and impact on children/school business.
 - Fire risk, if any.
 - Site Emergency Plan.
 - b) Monthly Site Meetings to monitor, review and share any new information including any new risks.
 - c) Site monitored daily whilst work is in progress by Clerk of Works / Health and Safety Officers.
 - d) Final Contractor review on completion of works undertaken.

Arson Prevention

- 1) Regular checks are undertaken by Caretakers / Cleaning Team(s) 365 days per year which helps reduce the risk of arson.
- 2) Restricted access to the premises by means of a door entry system.



- 3) There is no CCTV present.
- 4) There is no current evidence of arson.
- 5) The perimeter of the premises is well illuminated.
- 6) There have been no reported fire incidents since the last FRA.

Storage Arrangements

- 1) Residents instructed not to bring L.P.G cylinders into block. (Notice displayed in lifts see point 9-3)
- 2) The tenancy conditions, Section 7 Condition 5.6 stipulates "If you live in a flat or maisonette, you, people living with you and any visitors to your property must not keep or use paraffin oil, petrol, bottled gas appliances or any other explosive, FLAMMABLE or dangerous material in the property. This restriction also applies to any storage facility situated in or attached to the block, which has been provided for your use."
- 3) No Flammable liquids stored on site by Caretakers / cleaners.
- 4) All store cupboards are kept locked. The cleaner's storage is a steal cupboard secured under the staircase.



- 5) There are no flammable liquids or gas cylinders stored on site.
- 6) Residents have access to storage cupboards in the communal area.
- 7) Residents have access to outer storage cupboards.



Additional Control Measures; Fire Risk Assessment - Level 2 Action Plan

Significant Findings

Risk Rating of Additional Control Measures

	Risk Categories			
Risk Rating	Description			
5	Presents a serious risk to life safety. This matter requires immediate action and must be given a high priority.			
4	A significant safety issue.			
3	A safety issue, but where the level of risk is reduced by a combination of compensatory factors; or where there is a risk to property only.			
2	A desirable improvement to increase protection from fire.			
1	A minor improvement to safety.			

The highest risk rating selected shall be transferred to the front page of the risk assessment using a RAG rating as follows

Current Risk Rating 4-5 = HIGH

Current Risk Rating 1-3 = MEDIUM

Current Risk Rating 0 = Low



Fire Risk Assessment Level 2 Action Plan



Name of Premises or Location:

Martley Road 36-46, 48-58, Oldbury

Date of Action Plan:

18/08/2022

Review Date:

<Insert date>

Question/ Ref No	Required Action	Supporting photograph	Risk Rating	Timescale and Person Responsible	Date Completed
07/16	Removal of child seat left under staircase in block 48-58.	The state of the s	1	August 2022 caretakers	29/08/2022

07/17	Contact Tennent about the removal of plastic decorations and wicker hanging basket outside flat 48.	2	August 2022 Housing management team	03/10/2022
07/18	Contact tenant about the removal of pushchair/bike and other combustibles left outside flat 56 as well as wicker hanging basket.	2	August 2022 Housing management team	03/10/2022

09/1	Install emergency lighting in both blocks.	N/A	2	Future upgrade plan	N/a
10/06	Fire stopping required within the common loft space of both blocks.		3	September 2022 Fire rapid response team JM9574574 – asb check JM9574525	07/10/2022

Signed

Henning	Fire Risk Assessor	Date: 18/08/2022
@Morpan.	Premise Manager	Date: 26/08/2022

Name of property: Martley Road 36-46, 48-58

Updated: <insert date>

Premise Manager: Tony Thomson Tel. No.: 0121 569 2975

Hazard	Location	Information/Comments
Asbestos	Various locations	Asbestos has been labelled and Asbestos Survey undertaken and reports placed in motor room
An asbestos survey has been undertaken and no suspected A.C.M.'s were found to any of the communal areas. Survey held by S.M.B.C. Investment Division (Derek Still Tel:- 0121 569 5077).		