

# Fire Risk Assessment

## Hackwood Road



**Flats 42 – 48  
Hackwood Road,  
Wednesbury,  
WS10 0DG.**

**Date Completed: 07/08/2024.**

**Review Period: 3 years.**

**Officer: A Jones Fire Risk Assessor**

**Checked By: J Blewitt Team Lead Fire Safety & Facilities**

**Current Risk Rating = Trivial**



**Subsequent reviews.**

<b><u>Review date</u></b>	<b><u>Officer</u></b>	<b><u>Comments</u></b>

## Contents

<a href="#">Section 0</a>	<b>Introduction</b>	
<a href="#">Section 1</a>	<b>Significant Findings (executive summary)</b>	
<a href="#">Section 2</a>	<b>People at Significant Risk of Fire</b>	
<a href="#">Section 3</a>	<b>Contact Details</b>	
<a href="#">Section 4</a>	<b>Description of Premises</b>	
<a href="#">Section 5</a>	<b>Building Plan</b>	
<a href="#">Section 6</a>	<b>External Envelope</b>	
<a href="#">Section 7</a>	<b>Means of Escape from Fire</b>	
<a href="#">Section 8</a>	<b>Fire Detection and Alarm Systems</b>	
<a href="#">Section 9</a>	<b>Emergency Lighting</b>	
<a href="#">Section 10</a>	<b>Compartmentation</b>	
<a href="#">Section 11</a>	<b>Fire Fighting Equipment</b>	
<a href="#">Section 12</a>	<b>Fire Signage</b>	
<a href="#">Section 13</a>	<b>Employee Training</b>	
<a href="#">Section 14</a>	<b>Sources of Ignition</b>	
<a href="#">Section 15</a>	<b>Waste Control</b>	
<a href="#">Section 16</a>	<b>Control and Supervision of Contractors and Visitors</b>	
<a href="#">Section 17</a>	<b>Arson Prevention</b>	
<a href="#">Section 18</a>	<b>Storage Arrangements</b>	
<a href="#">Section 19</a>	<b>Additional Control Measures. Fire Risk Assessment – Level 2 Action Plan</b>	
<a href="#">Appendix 1</a>	<b>Significant Hazards on Site and Information to be provided for the Fire Service Risk Rating of Block</b>	

## Section

# 0

## Introduction

The [Regulatory Reform \(Fire Safety\) Order 2005 \(RR\(FS\)O\)](#) places a legal duty on landlords to complete a fire risk assessment (FRA). Specifically, RR(FS)O article 9. — (1)

*“The responsible person must make a suitable and sufficient assessment of the risks to which relevant persons are exposed for the purpose of identifying the general fire precautions he needs to take to comply with the requirements and prohibitions imposed on him by or under this Order”.*

This fire risk assessment has been written to comply fully with the above legislation which is enforced locally by West Midlands Fire Service. If required, complaints can be made to them by telephone on 0121 380 7500 or electronically on <https://www.wmfs.net/our-services/fire-safety/#reportfiresafety>. In the first instance however, we would be grateful if you could contact us directly via [https://www.sandwell.gov.uk/info/200195/contact\\_the\\_council/283/feedb ack\\_and\\_complaints](https://www.sandwell.gov.uk/info/200195/contact_the_council/283/feedback_and_complaints) or by phone on 0121 569 6000.

The date of the fire risk assessment is on the front page, followed by any subsequent reviews. A recurring time frame is not set in legislation, but the Council will as a minimum review:

- High Risk Residential Buildings annually
- Other Buildings every 3 years

The council has procedures and policies in place that will trigger a review of the fire risk assessment. This then is recorded on the fire risk assessment. If the review suggests the fire risk assessment is not currently suitable and sufficient, then a new fire risk assessment will be undertaken and become the current fire risk assessment. The previous fire risk assessment will be retained in the building safety case for that building.

The following diagrams illustrate those procedures and persons that support the effective planning, organisation, control, monitoring, and review of the preventive and protective measures. This information is provided as required under the RR(FS)O.



The above processes and procedures are overseen by the Fire Safety, Manager who reports to the Head of Building Safety.

These managers attend the Building Safety and Compliance Group for scrutiny which is part of the governance structure below.

Governance Structure



To summarise the fire risk assessment, in this scenario the RR(FS)O requires the prescribed information to be recorded. The prescribed information is the significant findings of the fire risk assessment and those groups or persons especially at risk from fire. This is recorded here in [section 1](#). Also required to be recorded under article 11, are the fire safety arrangements for the planning, organisation, control, monitoring, and review of the preventative and protective measures. The information shown above is part of this requirement.

## Section

## 1

## Significant findings

The significant findings (executive summary) of the fire risk assessment include those measures that have been or will be undertaken by the responsible person in order to comply with the RR(FS)O 2005.

Groups of people especially at risk of fire include such people as remote or lone workers, at risk due to layout of the building, visitors, and contractors unfamiliar with the building layout as well as those with physical, sensory, or mental health issues.

A third requirement that under the order must be recorded is the fire safety arrangements. This is the effective planning, organisation, control, monitoring, and review of the preventive and protective measures. These are shown in the introduction.

### Significant findings

*Include a brief summary of protective and preventative measures where relevant along with any issues found.*

The escape strategy is '**Stay Put Unless**'. This means in the event of a fire in your flat you should evacuate. If there is a fire elsewhere in the building you should stay put unless you are affected by fire, smoke or you have been advised by the emergency services to leave.

Section number	Section Area	Individual Risk Level
<a href="#">Section 6</a>	<p><b>External Envelope</b></p> <p>The exterior of the buildings is predominantly traditional brick, concrete construction with pitched, tiled roof. Individual flat windows are UPVC double glazed units.</p> <p>Staircase windows are non-openable, single glazed, Georgian wired glass.</p>	Trivial

<a href="#">Section 7</a>	<p><b>Means of Escape from Fire</b> The means of escape staircase incorporates a final exit.</p>	Trivial
<a href="#">Section 8</a>	<p><b>Fire Detection and Alarm Systems</b> Early warning is limited to hard wired or battery smoke alarms within each of the resident's flats.</p>	Trivial
<a href="#">Section 9</a>	<p><b>Emergency Lighting</b> Emergency lighting is not provided in the staircase, additional lighting is provided.</p>	Trivial
<a href="#">Section 10</a>	<p><b>Compartmentation</b> The building is designed to provide as a minimum 1-hour vertical fire resistance and 1-hour horizontal fire resistance around flats. Doors are 30-minute nominal fire doors, including those in 1-hour rated walls.</p>	Trivial
<a href="#">Section 11</a>	<p><b>Fire Fighting Equipment</b> No firefighting provisions are provided within the premise.</p>	Trivial
<a href="#">Section 12</a>	<p><b>Fire Signage</b> Appropriate signage is in place, no further action required.</p>	Trivial
<a href="#">Section 13</a>	<p><b>Employee Training</b> All staff receive basic fire safety awareness training.</p>	Trivial
<a href="#">Section 14</a>	<p><b>Sources of Ignition</b> The fixed electrical installation should be tested every 5 years. At the time of the assessment, it was determined that the last EICR inspection of electrical equipment was carried out on 08/07/2020.</p>	Trivial



<a href="#">Section 15</a>	<p><b>Waste Control</b> Regular cleaning services take place at the block and regular checks from caretakers help with waste control at the block.</p>	<p>Trivial</p>
<a href="#">Section 16</a>	<p><b>Control and Supervision of Contractors and Visitors</b> Contractors are controlled centrally, and hot works permits are required where necessary.</p>	<p>Trivial</p>
<a href="#">Section 17</a>	<p><b>Arson Prevention</b> A secure door entry system is not provided to the premise at the front elevation, consideration should be given to upgrading to secure access as part of any refurbishment.</p>	<p>Trivial</p>
<a href="#">Section 18</a>	<p><b>Storage Arrangements</b> Residents should not store fuel or LPG Cylinders in their home or storage facilities. This documented in the tenancy agreement.</p>	<p>Trivial</p>

## Risk Level Indicator

The following simple risk level estimator is based on commonly used risk level estimator:

Likelihood of fire	Potential consequences of fire		
	Slight harm	Moderate harm	Extreme harm
Low	Trivial risk	Tolerable risk	Moderate risk
Medium	Tolerable risk	Moderate risk	Substantial risk
High	Moderate risk	Substantial risk	Intolerable risk

Considering the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from fire (likelihood of fire) at these premises is:

Low  Medium  High

In this context, a definition of the above terms is as follows:

**Low** Unusually low likelihood of fire because of negligible potential sources of ignition.

**Medium** Normal fire hazards (e.g., potential ignition sources) for this type of occupancy, with fire hazards generally subject to appropriate controls (other than minor shortcomings).

**High** Lack of adequate controls applied to one or more significant fire hazards, such as to result in significant increase in likelihood of fire.

Considering the nature of the premises and the occupants, as well as the fire protection and procedural arrangements observed at the time of this fire risk assessment, it is considered that the consequences for life safety in the event of fire would be:

Slight Harm  Moderate Harm  Extreme Harm

In this context, a definition of the above terms is as follows:

**Slight harm**                      Outbreak of fire unlikely to result in serious injury or death of any occupant (other than an occupant sleeping in a room in which a fire occurs).

**Moderate harm**                      Outbreak of fire could foreseeably result in injury including serious injury) of one or more occupants, but it is unlikely to involve multiple fatalities.

**Extreme harm**                      Significant potential for serious injury or death of one or more occupants.

Accordingly, it is considered that the risk to life from fire at these premises is:

Trivial     Tolerable     Moderate     Substantial     Intolerable

**Comments:**

In conclusion, the likelihood of a fire is at a medium level of risk prior to the implementation of the action plan because of the normal fire hazards that have been highlighted within the risk assessment.

When future refurbishments are carried out, there are a number of observations that would improve the building. These observations can be found at the end of this document on page 37/38.

After considering the use of the premise and the occupants within the block, the consequences for life safety in the event of a fire would be slight harm.

A suitable risk-based control plan should involve effort and urgency that is proportional to risk. The following risk- based control plan is based on one that has been advocated for general health and safety risks:

Risk level	Action and timescale
<b>Trivial</b>	No action is required, and no detailed records need to be kept.
<b>Tolerable</b>	No major additional fire precautions required. However, there might be a need for reasonably practicable improvements that involve minor or limited cost.
<b>Moderate</b>	It is essential that efforts are made to reduce the risk. Risk reduction measures, which should take cost into account, should be implemented within a defined time. Where moderate risk is associated with consequences that constitute extreme harm, further assessment might be required to establish more precisely the likelihood of harm as a basis for determining the priority for improved control measures.
<b>Substantial</b>	Considerable resources might have to be allocated to reduce the risk. If the premises are unoccupied, it should not be occupied until the risk has been reduced. If the premises are occupied, urgent action should be taken.
<b>Intolerable</b>	Premises (or relevant area) should not be occupied until the risk is reduced.

***(Note that, although the purpose of this section is to place the fire risk in context, the above approach to fire risk assessment is subjective and for guidance only. All hazards and deficiencies identified in this report should be addressed by implementing all recommendations contained in the following action plan. The fire risk assessment should be reviewed regularly.)***

## Section

# 2

## People at Significant Risk of Fire

Persons at significant risk of fire does not just refer to those people with physical, sensory, or mental health issues. It also includes those at risk due to the layout or features of the building such as inner rooms or dead-end conditions. Persons may also be at risk due to remote or lone working.

The RR(FS)O requires that these people are identified in any fire risk assessment.

Sandwell Council takes the health, safety and wellbeing of its colleagues, contractors, residents, and leaseholders seriously. It is our policy to exceed, where possible, the minimum health and safety requirements of the law.

Residents are responsible for letting us know whether they might need a Personal Emergency Evacuation Plan (PEEP). The Resident Engagement Officers (Fire Safety) will conduct an assessment visit upon request. Any risk-reduction measures that are found where a PEEP is necessary and completed will be documented and taken quickly.

With the consent of the resident, we will make a referral for West Midlands Fire Service to conduct a Safe and Well visit.

When a PEEP is in place, the relevant information will be kept in the secure Premise Information Box (High Rise Buildings only), which is set up to help WMFS in an emergency. The data is classified as level 1, which means it complies with the General Data Protection Regulations.

## Section

# 3

## Contact Details

The Chief Executive of Sandwell Metropolitan Borough Council has ultimate responsibility for the site as the responsible person identified by the RR(FS)O 2005.

The Chief Executive has put a structure in place to support the management of the site.

This includes the role of Building Safety Manager who has duties as defined within the Regulatory Reform (Fire Safety) Order 2005.

The contact names to support the management of the site are as follows:

### **Chief Executive**

Shokat Lal

### **Directorate of Place**

Alan Lunt

### **Assistant Director Building Compliance**

Phil Deery

### **Fire Safety Manager**

Tony Thompson

### **Team Lead Fire Safety**

Jason Blewitt

### **Fire Risk Assessor(s)**

Adrian Jones

Anthony Smith

Carl Hill

Louis Conway

### **Resident Engagement Officer - Fire Safety**

Abdul Monim Khan

Lee Mlilo

### **Housing Office Manager**

Rushpal Dhaliwal

*Please note, the above details are correct at the time of the production of the risk assessment and may be subject to change.*

## Section 4

# Description of Premises

Flats 42 – 48,  
Hackwood Road,  
Wednesbury,  
WS10 0DG.

### Description of the Property:

The communal, any workplace areas and the external envelope of the building are subject to the Regulatory Reform (Fire Safety) Order 2005 as confirmed by the Fire Safety Act 2021.

The enforcing authority is West Midlands Fire Service.

This low-rise block of flats constitutes two storeys (inclusive of the ground floor), each of the floors contain 2 dwellings. The building was constructed circa 1961.


The building are of traditional brick, concrete construction, double glazed UPVC window frames surmounted by a pitched, tiled roof.



The block has one main entrance that provides access to all flats, the main entrance is located at the front elevation.



The building has a single staircase & small communal area that serves dwellings on all floors.



There is a small electrical cupboard located on the first floor outside flat number 44.



The rear garden is secured by fencing; there are access gates at each side of the building. These gates are padlocked at all times.





There is access to the loft space from the first floor landing area, the hatch is secured by padlocks.



There are four internal store cupboards located on the ground floor, these are for storage of residents belongings.



With regard to waste, residents utilise wheely bins, these are located at the front of the premise a safe distance from the main building.

High/Low Rise	Low Rise
Number of Floors	2
Date of Construction	1961
Construction Type	Solid Brick Construction
Last Refurbished	2017
External Cladding	External Wall Insulation
Number of Lifts	None
Number of Staircases	One
Automatic Smoke Ventilation to communal area	None
Fire Alarm System	None
Refuse Chute	None
Access to Roof	Loft access first floor
Equipment on roof (e.g. mobile phone station etc)	None

### Persons at Risk

Residents / Occupants of 4 number of flats),  
 Visitors,  
 Sandwell MBC employees,  
 Contractors,  
 Service providers (e.g. meter readers, delivery people etc)  
 Statutory bodies (e.g. W.M.F.S, Police, and Ambulance)

**Section  
5**

**Building Plan**

A general plan showing the building location.



## Section 6

### External envelope

Following the introduction of the Fire Safety Act 2021, consideration needs to be given to the external envelope of the building for any fire risk. This predominantly means the external wall construction including any insulation filler. It also includes balconies and any other fixtures as well as doors and windows.

Below is a breakdown of the materials used within the external envelope and, as part of the external wall system.

It is deemed that the combination and application of these materials presents an acceptable level of fire risk.

- 1) The external envelope of the premises is predominantly traditional brick, concrete construction, surmounted by a pitched tiled roof.



- 2) Individual flat windows are UPVC double glazed window frames. The windows in the communal areas are timber framed windows, single glazed Georgian wired glass.



- 3) There are no balconies on any elevation of this building.

## Section 7

### Means of Escape from Fire

- 1) The building has a single staircase that provides the means of escape. The staircase is of adequate width (at least 950mm) and must be maintained clear to that width as a minimum.



- 2) The final exit doors are not fitted with a door entry system or other type of security device. Therefore, security/Arson could be an issue.



- 3) Communal areas should be kept free of flammable items. The communal areas should be checked on a regular basis by Caretaking / Cleaning teams and all items of rubbish removed.






- 4) An automatic smoke ventilation is not commissioned, and staircase windows are non-openable.




- 5) The same electrical service cupboard on the first floor should be upgraded to a fire resistant cabinet when any upgrades of the building are carried out.



- 6) Surface coatings to the walls in the communal areas appear to be Class 0 rated.
- 7) The building has sufficient passive controls that provide effective compartmentation in order to support a Stay Put Policy Therefore residents are advised to remain in their flat unless the fire directly affects them.
- 8) The means of escape are protected to prevent the spread of fire and smoke with a combination of nominal composite type entrance doors.



- 9) It was noted that a number of pairs of shoes were left outside flat 46, these should be removed or stored in a secure cupboard. (Email sent to housing).



- 10) There are no corridors within the means of escape that form part of a dead end.
- 11) At the time of the fire risk assessment, the resident from flat 42 provided information on the front door, this was to establish whether or not the doors have not been tampered with by residents etc.

There were no issues identified with the front door, the resident confirmed that the self-closer was present and the door closed as required.



- 12) The premises do not have emergency lighting installed; however standardised lighting is present. This is deemed acceptable due to the height of the building.
- 13) Any communal fire doors are subject to an annual check by the Fire Safety Rapid Response Team.
- 14) When any future upgrades of the building are carried out, consideration should be given to upgrading the storage cupboard doors in the communal area.

**Section**

**8**

**Fire Detection and Alarm Systems**

- 1) Early warning is limited to hard wired or battery smoke alarms within each of the resident's flats. The equipment is subjected to a cyclical test.
- 2) During the assessment, the assessor spoke with the resident of flat number 42 who confirmed that smoke detection was located in the Hallway, Living room & Kitchen.
- 3) Therefore, based on the above point, it should be assumed that smoke detection in resident's flats is installed to a LD2 Standard.

*For information*

*LD1 all rooms except wet rooms.*

*LD2 all-risk rooms e.g., Living Room, Kitchens, and Hallway.*

*LD3 Hallway only.*

- 4) There is no other effective means for detecting an outbreak of fire to communal areas. The reason for this is: -
  - I. Such systems may get vandalised.
  - II. False alarms would occur.
  - III. A Stay Put - Unless policy is in place.



---

**Section**

**9**

---

**Emergency Lighting**

---

- 1) This premise does not have emergency lighting installed; however standardised lighting is present. This is deemed acceptable due to the height of the building.
- 2) Any future upgrade works should consider the installation of emergency lighting.

## Section 10

# Compartmentation

*The high degree of fire separation between flats and the common parts is achieved by making each flat a fire-resisting enclosure. This is known as compartmentation. A compartment is simply a part of a building bounded by walls and floors that will resist the passage of fire for a specified period of time. The fire resistance of this construction is such that, normally, a fire will burn itself out before spreading to other parts of the building.*

1. The building is designed to provide as a minimum 1-hour vertical fire resistance and 1-hour horizontal fire resistance around flats. All flat entrance doors are 30-minute notional/nominal doors, including those in 1-hour rated walls.
- 2) Generally, the means of escape is protected from flats with the use of nominal rated composite doors. These doors should be upgraded to certified FD30's when the door replacement programme commences.
- 3) The fire stopping / compartmentation of the premises is subject to an annual inspection by the Fire Safety Rapid Response Team.
- 4) The building has sufficient passive controls that provide effective compartmentation to support a Stay Put -Unless policy. Therefore, residents are advised to remain in their flat unless the fire directly affects them or if they are advised to evacuate by the emergency services.
- 5) Access to the roof space could not be gained at the time of the assessment. A future date will be agreed where the Assessor will meet the trades team at the premise to carry out a survey of the Roof void.
- 6) Access was not gained to the roof void at the time of the assessment. A future date will be scheduled with the trade team to access the roof void with appropriate equipment. This is to establish whether or not compartmentation is sufficient.



## Section

# 11

## Fire Fighting Equipment

- 1) No firefighting provisions are provided within the premise.
- 2) The closest firefighting hydrant is located outside 68 Stonehouse Road, this is the junction of Stonehouse Road and Hackwood Road.



## Section

# 12

## Fire Signage

- 1) Communal fire doors display “Fire Door Keep Shut” where appropriate.
- 2) The fire escape routes are self-evident and therefore additional fire action notices are not required.
- 3) No smoking (Smoke Free England) signage is displayed at the front entrance to the premises.



# Section 13

## Employee & Resident Training/Provision of Information


- 1) All Caretaking / Cleaning Employees have undertaken fire safety training. This includes use of bespoke 'Fire Safety in High / Low Rise Flatted Accommodation' Video.
- 2) All employees are encouraged to complete 'In the line of fire' training on an annual basis.
- 3) Caretaking Teams are not currently trained in the effective use of fire extinguishers. Caretaking Teams are not expected to tackle fires in this area.
- 4) Employees within the Neighbourhoods Directorate assigned to undertake Fire Safety Inspections have received IFE approved training via West Midlands Fire Service.
- 5) Staff undertaking fire risk assessments are qualified to or working towards Level 4 Diploma in Fire Risk Assessment.
- 6) Fire safety information has been provided as part of tenancy pack. Information regarding the Stay Put Unless fire evacuation strategy is provided to tenants.



## Section 14

### Sources of Ignition

- 1) Smoking is prohibited within any communal parts of the building in line with Smoke Free England legislation.
- 2) Hot working is not normally conducted. If essential maintenance requires the use of hot work processes, then corporate policies and procedures are to be followed.
- 3) The fixed electrical installation should be tested every 5 years. At the time of the assessment, it was confirmed that the last electrical installation conditioning report (EICR) was carried out on 8<sup>th</sup> July 2020. The date of the next scheduled EICR inspection is July 2025.



- 4) Portable electrical equipment used as part of the Caretaking / Cleaning regime is subject to annual PAT Testing. This information is held by the Estate Services Manager Bryan Low.
- 5) Portable heaters are not allowed in any common parts of the premises.
- 6) Gas appliances and pipework (where installed) are subject to annual testing and certification. This cyclical contract is managed by the in-house Gas Team.
- 7) As per tenancy agreements, flammable liquids or gas cylinders should not be stored on site.

**Section**  
**15**

---

**Waste Control**

---

- 1) Refuse containers are emptied at regular intervals.
- 2) There is an 'Out of Hours' service in place to remove bulk items.

## Section 16

# Control and Supervision of Contractors and Visitors

- 1) Responsive Repairs service delivered by Sandwell MBC necessitates the production of an order via the computerised repairs system. Details of any known risks are documented on the repair order.
- 2) Owing to the nature of low-rise flatted accommodation it is difficult to manage/control individual contractors/utility companies.
- 3) Hot works are not permitted unless authorisation is given via the approved officer. The hot works procedure is to be followed.
- 4) Utility companies are not allowed to access any service cupboard or secure area. They must request and collect maintenance keys from the Investments office @ Roway Lane. This allows scrutiny of what is the scope of any works such as installation of tenant's broadband / phone line etc.
- 5) Where contractors are appointed to undertake major refurbishment works, Sandwell MBC Urban Design team will put control measures in place. Such Measures include: -
  - a) Pre-Contract Meetings – where contractor is made aware of all working arrangements and safe systems of work to be adopted. Issues covered in this meeting will include:
    - Health and Safety.
    - Site security.
    - Safety of working and impact on children/school business.
    - Fire risk, if any.
    - Site Emergency plan.
  - b) Monthly Site Meetings – to monitor, review and share any new information including any new risks.
  - c) Site monitored daily whilst work is in progress by Clerk of Works / Health and Safety Officers.
  - d) Final Contractor review on completion of works undertaken.



---

**Section**

**17**

---

**Arson Prevention**

---

- 1) Regular checks are undertaken by Caretakers / Cleaning Team(s) 365 days per year which helps reduce the risk of arson.
- 2) Access to the flats is not restricted by a door entry system. It is recommended that a secure door entry system is fitted to the building should any future upgrades of the building take place.
- 3) There have been no reported fire incidents since the last FRA.

## Section 18

### Storage Arrangements

- 1) Residents are instructed not to bring L.P.G cylinders into block. This information is contained within the tenants' handbook.
- 2) The tenancy conditions, Section 7 – Condition 5.6 stipulates “If you live in a flat or maisonette, you, people living with you and any visitors to your property must not keep or use paraffin oil, petrol, bottled gas appliances or any other explosive, FLAMMABLE, or dangerous material in the property. This restriction also applies to any storage facility situated in or attached to the block, which has been provided for your use.”
- 3) No Flammable liquids stored on site by Caretakers / Cleaners.
- 4) Most store/service cupboards are kept locked, these doors were in good condition at the time of the assessment.
- 5) As per tenancy agreements, flammable liquids or gas cylinders should not be stored on site.

**Section  
19**

**Additional Control Measures.  
Fire Risk Assessment - Level 2  
Action Plan**

Significant Findings

**Action Plan.**

It is considered that the following recommendations should be implemented to reduce fire risk to, or maintain it at, the following level:

Trivial       Tolerable

Definition of priorities (where applicable):

P1 Arrange and complete as urgent – Within 10 days.

P2 Arrange and complete within 1-3 Months of assessment date.

P3 Arrange and complete within 3-6 Months of assessment date.

P4 Arrange and complete exceeding 6 months under programmed work.



# Fire Risk Assessment Level 2 Action Plan



Name of Premises or Location:

Flats 42 – 48, Hackwood Road, Wednesbury.

Date of Action Plan:




07/08/2024

Review Date:

<Insert date>

Question/ Ref No	Required Action	Supporting photograph	Priority	Timescale and Person Responsible	Date Completed	
		No Action Points within this Fire Risk Assessment.				

When undertaking future improvement program(s), it is advised that the observations listed below should be given consideration (noting that the safety of the residents is not jeopardised by these, and all steps to reduce any known risks have been taken).

<b>Observations</b>	
<p>Internal store cupboards doors should be upgraded to FD30s as part of next improvement works programme.</p>	
<p>As part of any future upgrades the service cupboard on the first floor should be upgraded to a material that offers adequate fire resistance.</p>	
<p>As part of any future upgrades or door replacement programme, consideration should be given to providing a suitable electronic door entry system to offer greater security to the building.</p>	

Fire Risk Assessment



Access to the roof space could not be gained at the time of the assessment. A future date will be agreed where the Assessor will meet the trades team at the premise to carry out a survey of the Roof void.



As part of any future upgrade work consider should be given to the installation emergency lighting.

N/A.

**Signed**

 Adrian Jones	Fire Risk Assessor	Date: 07/08/2024
	Quality Assurance Check	Date: 12/08/2024




## Significant Hazards on Site and Information to be Provided for the Fire Service

**Name of property:** Flats 42 – 48, Hackwood Road, Wednesbury.

**Updated:**

**Premise Manager:** Tony Thompson. **Tel. No.:** 0121 569 2975

Hazard	Information/Comments
Asbestos	An asbestos survey has been undertaken of the communal areas. Survey held by Sandwell Housing (Derek Still <a href="tel:01215695077">Tel:- 0121 569 5077</a> ).

<b>Asbestos Survey</b>		Property Address	42-48 Hackwood Road Wednesbury, WS10 0DG.		Office use <input checked="" type="checkbox"/>					
Surveyed by	Gary Carrington	Date	19/03/14		Checked by	DEREK STILL	Desktop Check	<input checked="" type="checkbox"/>	Site Check	<input type="checkbox"/>
Reason for request		HSG 264 - Survey Report Type		Date	19/05/2020					
Investment Void		Refurbishment Survey		Property Description  2 Storey Block						
Investment Tenanted		Management Survey				<input checked="" type="checkbox"/>				
R & M Void		SHAPE Interrogated.				<input checked="" type="checkbox"/>				
R & M Tenanted		No Existing SHAPE Data.								
Medical / Emergency - Heating Works		Existing SHAPE Data.				<input checked="" type="checkbox"/>				
Communal Areas	<input checked="" type="checkbox"/>	Refurb Surveys Interrogated ?								
		Year Built	1961							
						Notes / including details of similar property surveys completed. No access to ground floor communal store cupboards x 4. Revised by G.Carrington – 11/08/2022				
Building Surveyors 0121 569 5077						Asset Team – Investment Division Operations & Development Centre Roway Lane Oldbury B69 3ES				
										

## Fire Risk Assessment

Sample Locations	Property Address	42-48 Hackwood Road, Wednesbury, WS10 0DG.						
LOCATION	MATERIAL	QTY	SURFACE TREATMENT	SAMPLE REF	RESULT	HSE NOTIFY	Labelled ?	ACTION TAKEN ON CONTRACT
IF DURING THE COURSE OF WORK SUSPECTED ACM'S ARE IDENTIFIED THAT ARE NOT CONTAINED WITHIN THIS REPORT STOP WORK & SEEK ADVICE								
FRONT ENTRANCE CANOPY INTERNAL SOFFIT	CEMENT	2 m <sup>2</sup>	SEALED	PRESUMED	CHRYSOTILE	NO	-	-
REAR ENTRANCE CEILING ADJACENT TO STORE CUPBOARDS	CEMENT	4 m <sup>2</sup>	SEALED	PRESUMED	CHRYSOTILE	NO	-	-
GROUND FLOOR STORE SHED CEILINGS	CEMENT	6 m <sup>2</sup>	SEALED	PRESUMED	CHRYSOTILE	NO	-	-
1 <sup>ST</sup> FLOOR COMMUNAL CEILING	CEMENT	20 m <sup>2</sup>	SEALED	PRESUMED	CHRYSOTILE	NO	-	-
MAIN ROOF SOFFITS	CEMENT	20 m <sup>2</sup>	SEALED	PRESUMED	CHRYSOTILE	NO	-	-
FLAT 42 FRONT DOOR FRAME SEAL	MASTIC	-	SEALED	SH989 / 1	NO ASBESTOS DETECTED	-	-	-
FLAT 44 FRONT DOOR FRAME SEAL	MASTIC	-	SEALED	SH970 / 1	NO ASBESTOS DETECTED	-	-	-
FLAT 46 FRONT DOOR FRAME SEAL	MASTIC	-	SEALED	SH971 / 1	NO ASBESTOS DETECTED	-	-	-
FLAT 48 FRONT DOOR FRAME SEAL	MASTIC	-	SEALED	SH972 / 1	NO ASBESTOS DETECTED	-	-	-
ITEMS SHOWN BELOW HAVE BEEN ASSESSED ON SITE BY THE ASBESTOS SURVEYOR & ARE CONFIRMED NOT TO BE ACM'S.								
LOCATION DESCRIPTION	MATERIAL	LOCATION DESCRIPTION	MATERIAL	LOCATION DESCRIPTION	MATERIAL			
COMMUNAL WALLS	AGGREGATE RENDER	MAIN ROOF SOFFITS	UPVC					
REAR SHED ROOFS	MINERAL FELT							
FRONT CANOPY ROOF	MINERAL FELT							
1 <sup>ST</sup> FLOOR HIGH LEVEL METER CUPBOARD	PLYWOOD							
FRONT CANOPY INTERNAL SOFFIT	PLASTERBOARD							