

Fire Risk Assessment

Waterside 1-10

West Bromwich,

B43 5PQ.



Date Completed: 30th September 2024

Review Period: 3 years.

Officer: A Smith **Fire Risk Assessor**

Checked By: A. Jones **Fire Risk Assessor**

Current Risk Rating = Trivial

Subsequent reviews

<u>Review date</u>	<u>Officer</u>	<u>Comments</u>

Contents

Section 0	Introduction	
Section 1	Significant Findings (executive summary)	
Section 2	People at Significant Risk of Fire	
Section 3	Contact Details	
Section 4	Description of Premises	
Section 5	Building Plan	
Section 6	External Envelope	
Section 7	Means of Escape from Fire	
Section 8	Fire Detection and Alarm Systems	
Section 9	Emergency Lighting	
Section 10	Compartmentation	
Section 11	Fire Fighting Equipment	
Section 12	Fire Signage	
Section 13	Employee Training	
Section 14	Sources of Ignition	
Section 15	Waste Control	
Section 16	Control and Supervision of Contractors and Visitors	
Section 17	Arson Prevention	
Section 18	Storage Arrangements	
Section 19	Additional Control Measures. Fire Risk Assessment – Action Plan.	
Appendix 1	Significant Hazards on Site and Information to be provided for the Fire Service Risk Rating of Block	

Section

0

Introduction

The [Regulatory Reform \(Fire Safety\) Order 2005 \(RR\(FS\)O\)](#) places a legal duty on landlords to complete a fire risk assessment (FRA). Specifically, RR(FS)O article 9. — (1) *“The responsible person must make a suitable and sufficient assessment of the risks to which relevant persons are exposed for the purpose of identifying the general fire precautions he needs to take to comply with the requirements and prohibitions imposed on him by or under this Order”*.

This type 1 fire risk assessment has been written to comply fully with the above legislation which is enforced locally by West Midlands Fire Service. If required, complaints can be made to them by telephone on 0121 380 7500 or electronically on <https://www.wmfs.net/our-services/fire-safety/#reportfiresafety>. In the first instance however, we would be grateful if you could contact us directly via https://www.sandwell.gov.uk/info/200195/contact_the_council/283/feedb ack_and_complaints or by phone on 0121 569 6000.

The date of the fire risk assessment is on the front page, followed by any subsequent reviews. A recurring time frame is not set in legislation, but the Council will as a minimum review:

- High Risk Residential Buildings annually
- Other Buildings every 3 years

The council has procedures and policies in place that will trigger a review of the fire risk assessment. This then is recorded on the fire risk assessment. If the review suggests the fire risk assessment is not currently suitable and sufficient, then a new fire risk assessment will be undertaken and become the current fire risk assessment. The previous fire risk assessment will be retained in the building safety case for that building.


The following diagrams illustrate those procedures and persons that support the effective planning, organisation, control, monitoring and review of the preventive and protective measures. This information is provided as required under the RR(FS)O.



The above processes and procedures are overseen by the Fire Safety, Manager who reports to the Head of Building Safety

These managers attend the Building Safety and Compliance Group for scrutiny which is part of the governance structure below.

Governance Structure



To summarise the fire risk assessment, in this scenario the RR(FS)O requires the prescribed information to be recorded. The prescribed information is the significant findings of the fire risk assessment and those groups or persons especially at risk from fire. This is recorded here in [section 1](#). Also required to be recorded under article 11, are the fire safety arrangements for the planning, organisation, control, monitoring and review of the preventative and protective measures. The information shown above is part of this requirement.

Section

1

Significant findings

The significant findings (executive summary) of the fire risk assessment include those measures that have been or will be undertaken by the responsible person in order to comply with the RR(FS)O 2005. Groups of people especially at risk of fire include such people as remote or lone workers, at risk due to layout of the building, visitors and contractors unfamiliar with the building layout as well as those with physical, sensory or mental health issues. A third requirement that under the order must be recorded is the fire safety arrangements. This is the effective planning, organisation, control, monitoring and review of the preventive and protective measures. These are shown in the introduction.

Significant findings

Include a brief summary of protective and preventative measures where relevant along with any issues found;

The escape strategy is '**Stay Put Unless**'. This means in the event of a fire in your flat you should evacuate. If there is a fire elsewhere in the building you should stay put unless you are affected by fire, smoke or you have been advised by the emergency services to leave.

Section number	Section Area	Individual Risk Level
Section 6	<p>External Envelope Each façade of the building comprises of traditional brick masonry and concrete construction.</p> <p>Individual flat windows and those to communal areas are UPVC double glazed units.</p>	Trivial

Section 7	<p>Means of Escape from Fire The open deck access block has one staircase.</p> <p>Maisonette entrance doors opening onto deck access are nominal 30-minute fire doors.</p>	<p>Trivial</p>
Section 8	<p>Fire Detection and Alarm Systems Maisonettes have a fire detection system fitted to an LD2 standard.</p>	<p>Trivial</p>
Section 9	<p>Emergency Lighting This block has no emergency lighting provision. This is deemed acceptable in this low-rise block.</p>	<p>Trivial</p>
Section 10	<p>Compartmentation The blocks have sufficient compartmentation between dwellings.</p>	<p>Trivial</p>
Section 11	<p>Fire Fighting Equipment The premises have no provision for firefighting equipment.</p>	<p>Trivial</p>
Section 12	<p>Fire Signage Due to simplicity of layout no requirement for fire signage.</p>	<p>Trivial</p>
Section 13	<p>Employee Training All staff receive basic fire safety awareness training.</p>	<p>Trivial</p>
Section 14	<p>Sources of Ignition The fixed electrical installation should be tested every 5 years. The next test date is scheduled for October 2024.</p>	<p>Trivial</p>

Section 15	Waste Control Refuse containers are emptied regularly. There is a regular cleaning service to the premises.	Trivial
Section 16	Control and Supervision of Contractors and Visitors Contractors are controlled centrally, and hot works permits are required where necessary.	Trivial
Section 17	Arson Prevention Door entry system is evident. External lighting is in place.	Trivial
Section 18	Storage Arrangements Residents instructed not to bring L.P.G cylinders into block.	Trivial

Risk Level Indicator

The following simple risk level estimator is based on commonly used risk level estimator:

Likelihood of fire	Potential consequences of fire		
	Slight harm	Moderate harm	Extreme harm
Low	Trivial risk	Tolerable risk	Moderate risk
Medium	Tolerable risk	Moderate risk	Substantial risk
High	Moderate risk	Substantial risk	Intolerable risk

Considering the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from fire (likelihood of fire) at these premises is:

Low Medium High

In this context, a definition of the above terms is as follows:

Low Unusually low likelihood of fire because of negligible potential sources of ignition.

Medium Normal fire hazards (e.g., potential ignition sources) for this type of occupancy, with fire hazards generally subject to appropriate controls (other than minor shortcomings).

High Lack of adequate controls applied to one or more significant fire hazards, such as to result in significant increase in likelihood of fire.

Considering the nature of the premises and the occupants, as well as the fire protection and procedural arrangements observed at the time of this fire risk assessment, it is considered that the consequences for life safety in the event of fire would be:

Slight Harm Moderate Harm Extreme Harm

In this context, a definition of the above terms is as follows:

Slight harm	Outbreak of fire unlikely to result in serious injury or death of any occupant (other than an occupant sleeping in a room in which a fire occurs).
Moderate harm	Outbreak of fire could foreseeably result in injury including serious injury) of one or more occupants, but it is unlikely to involve multiple fatalities.
Extreme harm	Significant potential for serious injury or death of one or more occupants.

Accordingly, it is considered that the risk to life from fire at these premises is:

Trivial Tolerable Moderate Substantial Intolerable

Comments

In conclusion, the likelihood of fire is at a low level of risk. No fire incidents have been reported for this block.

After considering the use of the premise and the occupants the consequences for life safety in the event of a fire would be slight harm.

This is due to there being a Stay Put Unless policy and sufficient compartmentation to include nominal FD30s doors to the open deck and suitable smoke detection to LD2 standard within maisonettes.

Overall, the level of risk at the time of this FRA is Trivial.

A suitable risk-based control plan should involve effort and urgency that is proportional to risk. The following risk-based control plan is based on one that has been advocated for general health and safety risks:

Risk level	Action and timescale
Trivial	No action is required, and no detailed records need to be kept.
Tolerable	No major additional fire precautions required. However, there might be a need for reasonably practicable improvements that involve minor or limited cost.
Moderate	It is essential that efforts are made to reduce the risk. Risk reduction measures, which should take cost into account, should be implemented within a defined time period. Where moderate risk is associated with consequences that constitute extreme harm, further assessment might be required to establish more precisely the likelihood of harm as a basis for determining the priority for improved control measures.
Substantial	Considerable resources might have to be allocated to reduce the risk. If the premises are unoccupied, it should not be occupied until the risk has been reduced. If the premises are occupied, urgent action should be taken.
Intolerable	Premises (or relevant area) should not be occupied until the risk is reduced.

(Note that, although the purpose of this section is to place the fire risk in context, the above approach to fire risk assessment is subjective and for guidance only. All hazards and deficiencies identified in this report should be addressed by implementing all recommendations contained in the following action plan. The fire risk assessment should be reviewed regularly.)

Section

2

People at Significant Risk of Fire

Persons at significant risk of fire does not just refer to those people with physical, sensory or mental health issues. It also includes those at risk due to the layout or features of the building such as inner rooms or dead-end conditions. Persons may also be at risk due to remote or lone working.

The RR(FS)O requires that these people are identified in any fire risk assessment.

Sandwell Council takes the health, safety and wellbeing of its colleagues, contractors, residents and leaseholders seriously. It is our policy to exceed, where possible, the minimum health and safety requirements of the law.

Residents are responsible for letting us know whether they might need a Personal Emergency Evacuation Plan (PEEP). The Resident Engagement Officers (Fire Safety) will conduct an assessment visit upon request. Any risk-reduction measures that are found where a PEEP is necessary and completed will be documented and taken quickly. With the consent of the resident, we will make a referral for West Midlands Fire Service to conduct a Safe and Well visit.

When a PEEP is in place, the relevant information will be kept in the secure Premise Information Box (High Rise Buildings only), which is set up to help WMFS in an emergency. The data is classified as level 1, which means it complies with the General Data Protection Regulations.

Section

3

Contact Details

The Chief Executive of Sandwell Metropolitan Borough Council has ultimate responsibility for the site as the responsible person identified by the RR(FS)O 2005.

The Chief Executive has put a structure in place to support the management of the site.

This includes the role of Building Safety Manager who has duties as defined within the Regulatory Reform (Fire Safety) Order 2005.

The contact names to support the management of the site are as follows:

Chief Executive

Shokat Lal

Executive Director of Place

Alan Lunt

Assistant Director Asset Management & Improvement

Sarah Ager

Fire Safety Manager

Tony Thompson

Team Lead Fire Safety

Jason Blewitt

Fire Risk Assessor(s)

Adrian Jones

Anthony Smith

Carl Hill

Louis Conway

Resident Engagement Officer - Fire Safety

Abdul Monim Khan

Housing Office Manager

Lisa Ellis.

Please note, the above details are correct at the time of the production of the risk assessment and may be subject to change

Section 4

Description of Premises


Waterside 1-10
Great Barr
West Bromwich
B43 5PQ.

Description of the Property

The low-rise property was built in 1968. The block consists of 4 storeys (inclusive of the ground floor).

The block consists of 5 ground floor maisonettes and 5 second floor maisonettes.

The block has a main entrance to the front elevation. The front entrance has a door entry system with a fob reader installed. There is drop latch key for firefighting access.



The property has a pitched roof with no communal access. The staircase has a pitched roof with no communal access.



The communal, any workplace areas and the external envelope of the building are subject to the Regulatory Reform (Fire Safety) Order 2005 as confirmed by the Fire Safety Act 2021.

The enforcing authority is West Midlands Fire Service.

High/Low Rise	Low Rise
Number of Floors	4
Date of Construction	1968
Construction Type	System built (Wimpey).
Last Refurbished	Unknown
External Cladding	None
Number of Lifts	None
Number of Staircases	One
Automatic Smoke Ventilation to communal area	None
Fire Alarm System	None
Refuse Chute	None
Access to Roof	No access from communal areas.
Equipment on roof (e.g., mobile phone station etc)	None

Persons at Risk

Residents / Occupants of 10 Maisonettes.

Visitors,

Sandwell MBC employees,

Contractors,

Service providers (e.g., meter readers, delivery people etc)

Statutory bodies (e.g., W.M.F.S, Police, and Ambulance)

Section
5

Building Plan

General plan which outlines the buildings footprint.



Section 6

External envelope

Following the introduction of the Fire Safety Act 2021, consideration needs to be given to the external envelope of the building for any fire risk. This predominantly means the external wall construction including any insulation filler. It also includes balconies and any other fixtures as well as doors and windows.

Below is a breakdown of the materials used within the external envelope and, as part of the external wall system.

It is deemed that the combination and application of these materials presents an acceptable level of fire risk.


- 1) The exterior of the building is predominantly traditional brick gable construction with what is presumed to be rear and front concrete rendered walls. The rear open access deck is of concrete construction.



- 2) Individual communal windows to the stairs are UPVC (Non openable as no handles).



- 3) Front entrance doors opening onto rear open deck access are predominately nominal FD 30s self-closing composite and timber fire doors. Entrance doors at ground floor level are standard non fire rated UPVC doors.



- 4) The block has a pitched concrete tiled roof.



**Section
7**

Means of Escape from Fire

- 1) The site has one staircase that provides a means of escape.



- 2) The means of escape (rear single travel open deck) are protected to prevent the spread of fire and smoke with predominately nominal timber and composite self-closing FD 30s fire doors. No internal access to maisonettes was gained during the fire risk assessment. Resident to flat 2 did allow an inspection of the maisonette entrance door. Resident confirmed smoke detection provision (not inspected).



Definitions Fire Doors.

Notional fire door - A fire door that is thought to have been installed at the time of construction. This door may not meet current building regulation requirements however is still acceptable if performing as originally intended.

Upgraded notional fire door - A notional fire door that has been upgraded. For example, with intumescent strips and cold smoke seals.

Nominal fire door – A fire door that may meet the standards specified within the building regulations but have not been awarded the official certification of doors manufactured and tested by an accredited, third-party testing unit and approved formally with the relevant certificates and documentation.

Certified fire door – A fire door and frame that have been approved and certified by the manufacturer. The door assembly must be installed by a competent person.

- 3) Wall construction on external escape route, is approx. 1100mm to bottom of window. This is deemed acceptable for a person to crouch and pass the window. Please note a stay put unless strategy applies to this building.



- 4) Automatic smoke ventilation is not employed. This is acceptable as the deck is open to air.



- 5) Communal areas are kept free of flammable items. The communal areas are checked on a regular basis by Janitorial/ Cleaning teams. There is also an out of hours service that allows combustible items of furniture / rubbish to be removed.
-

Good housekeeping is fundamental to reducing risk in blocks of flats. Controlling the presence of combustibile materials and ignition sources not only reduces the potential for accidental fires to start and develop in the common parts, it also significantly reduces the scope for deliberate fires. It also ensures escape routes are free of obstructions that might hinder the evacuation of people from the building and access for fire-fighters.

- 6) Emergency lighting is not provided to the staircase or open deck. This is deemed acceptable in this low-rise block. Consideration should be given to an emergency lighting installation as part of a future upgrade works.



- 7) The building has sufficient passive controls that provide effective compartmentation in order to support a Stay Put-Unless Policy. Therefore, residents are advised to remain in their flat unless the fire directly affects them or if they are advised to evacuate by the emergency services.

Section

8

Fire Detection and Alarm Systems

- 1) Early warning is limited to hard wire or battery smoke alarms within each of the resident's flats. The equipment is subjected to a cyclical test.
- 2) No internal access to maisonettes was gained during this fire risk assessment. However, resident to flat 2 confirmed LD2 standard. Resident confirmed smoke detection located: top of stairs, Hall, living room and kitchen.

For information

LD1 all rooms except wet rooms

LD2 all-risk rooms e.g., Living Room, Kitchens and Hallway.

LD3 Hallway only

- 3) There is no effective means for detecting an outbreak of fire to communal areas in the remaining blocks. The reason for this is:
 - I. Such systems may get vandalised.
 - II. False alarms would occur.
 - III. A Stay Put - Unless policy is in place.

Section 9

Emergency Lighting

- 1) The premises has no provision for emergency lighting to the open deck or staircase. Consideration should be given to an emergency lighting installation as part of a future works programme.



Section 10

Compartmentation

This section should be read in conjunction with Section 4

- 1) The building is designed to provide as a minimum 60-minute vertical fire resistance and 60-minute horizontal fire resistance. Please note the block is designed as open deck access therefore it is acceptable for non-fire rated windows to be adjacent to the deck. It is acceptable to have 30-minute flat entrance doors in a 60-minute wall.
 - 2) The premises do not have sufficient compartmentation to limit the travel and effect of smoke and flame in event of a fire in communal areas due to the open plan staircase.
 - 3) A variety of methods / materials have been used to achieve fire-stopping including Rockwool, fire rated sponge and intumescent pillows.
-

Fire Risk Assessment

- 4) The fire stopping / compartmentation is subject to an annual check by the Fire Safety Rapid Response Team.
- 5) Any remedial works arising from the fire stopping / compartmentation check(s) will be actioned immediately by the Fire Safety Rapid Response Team.
- 6) The building has sufficient passive controls that provide effective compartmentation to support a Stay Put -Unless policy. Therefore, residents are advised to remain in their flat unless the fire directly affects them or if they are advised to evacuate by the emergency services.

Floor No	Electrical							Comms Riser							Fire Stopping Materials							Fire Stopping Materials							Fire Stopping Materials							Floor No																																									
	Supalux	Inu Batt	Inu Sponge	Inu AM Mastic	Graphite Filler	Inu Pads	Inu Wraps	Recesswool	Supalux	Inu Batt	Inu Sponge	Inu AM Mastic	Graphite Filler	Inu Pads	Inu Wraps	Recesswool	Supalux	Inu Batt	Inu Sponge	Inu AM Mastic	Graphite Filler	Inu Pads	Inu Wraps	Recesswool	Supalux	Inu Batt	Inu Sponge	Inu AM Mastic	Graphite Filler	Inu Pads	Inu Wraps	Recesswool	Supalux	Inu Batt	Inu Sponge		Inu AM Mastic	Graphite Filler	Inu Pads	Inu Wraps	Recesswool																																				
B																																									B																																				
G			✓																																						G																																				
1								✓			✓	✓																													1																																				
2																																									2																																				
3																																									3																																				
4																																									4																																				
5																																									5																																				
6																																									6																																				
7																																									7																																				
8																																									8																																				
9																																									9																																				
10																																									10																																				
11																																									11																																				
12																																									12																																				
13																																									13																																				
14																																									14																																				
15																																									15																																				
16																																									16																																				
Communal doors free from defects	✓							Communal windows free from defects							✓							Flat doors free from defects							✓							Communal cupboards locked and secure							✓							Communal areas free from tenants stored items							✓							Communal areas free from repair materials							✓						
Foam Removal & Enhancement Record													Foam, Enhancements & Other Comments:																																																																
Foam Present But Not Removed This Visit																																																																													
Foam Present & Partially Removed This Visit																																																																													
Foam Present & Fully Removed This Visit																																																																													
No Foam Present													✓																																																																
No Enhancement Carried Out This Visit													✓																																																																
Enhancement Carried Out This Visit																																																																													

- 7) Individual maisonette doors which open onto the deck access are predominantly nominal Composite and timber fire doors.

Refer to updated door spreadsheet below.

Waterside 1-10 (O&E)	BL51484WA1: 1-10 Waterside;Great Barr;Birmingham;;	Intentionally Blank
Waterside 1-10 (O&E)	BL51484WA1: 1 Waterside;Great Barr;Birmingham;;	Timber Door FD30s Not Glazed
Waterside 1-10 (O&E)	BL51484WA1: 2 Waterside;Great Barr;Birmingham;;	Composite Glazed
Waterside 1-10 (O&E)	BL51484WA1: 3 Waterside;Great Barr;Birmingham;;	Timber Door FD30s Not Glazed
Waterside 1-10 (O&E)	BL51484WA1: 4 Waterside;Great Barr;Birmingham;;	Timber Door FD30s Not Glazed
Waterside 1-10 (O&E)	BL51484WA1: 5 Waterside;Great Barr;Birmingham;;	Hurst Door Not Glazed
Waterside 1-10 (O&E)	BL51484WA1: 6 Waterside;Great Barr;Birmingham;;	UPVC Glazed
Waterside 1-10 (O&E)	BL51484WA1: 7 Waterside;Great Barr;Birmingham;;	UPVC Glazed
Waterside 1-10 (O&E)	BL51484WA1: 8 Waterside;Great Barr;Birmingham;;	UPVC Glazed
Waterside 1-10 (O&E)	BL51484WA1: 9 Waterside;Great Barr;Birmingham;;	UPVC Glazed
Waterside 1-10 (O&E)	BL51484WA1: 10 Waterside;Great Barr;Birmingham;;	UPVC Glazed

- 8) There is no means of access to the internal roof space from the common areas.
- 9) Notional cupboard doors should be considered for upgrading to a certified FD 30s door set, during the next programmed works. No access was gained during this risk assessment.



Section 11

Fire Fighting Equipment

- 1) The premise has no provision for firefighting equipment.

Section
12

Fire Signage

- 1) Fire Action Notices are not displayed throughout the building. The signs are not required due to the building not having a complex layout.
- 2) Smoking is prohibited within any communal parts of the building in line with Smoke Free England Legislation.



- 3) Yellow LPG warning signs are not displayed.
-

**Section
13**

**Employee & Resident
Training/Provision of Information**

- 1) All Caretaking / Cleaning Employees have undertaken fire safety training. This includes use of bespoke 'Fire Safety in High / Low Rise Flatted Accommodation' Video.
- 2) All employees are encouraged to complete 'In the line of fire' training on an annual basis.
- 3) Caretaking Teams are not currently trained in the effective use of fire extinguishers. Caretaking Teams are not expected to tackle fires in this area.
- 4) Staff undertaking fire risk assessments are qualified to Level 4 Diploma in Fire Safety.
- 5) Fire safety information has been provided as part of tenancy pack.
- 6) Information regarding use of fire doors is provided to residents.



- 7) Information regarding the Stay Put unless fire evacuation strategy is provided to residents.



Section

14

Sources of Ignition

- 1) Smoking is prohibited within any communal parts of the building in line with Smoke Free England legislation.
- 2) Hot working is not normally carried out. If essential maintenance requires the use of hot work processes, then corporate policies and procedures are to be followed.
- 3) Portable electrical equipment used as part of the Caretaking / Cleaning regime is subject to annual PAT Testing. This information is held by the Estate Services Manager Bryan Low.
- 4) The fixed electrical installation shall be tested every 5 years. The next scheduled test is October 2024.
- 5) Portable heaters are not allowed in any common parts of the premises.
- 6) Gas appliances and pipework (where installed) are subject to annual testing and certification. This cyclical contract is managed by the in-house Gas Team. Gas supply is external.



Section
15

Waste Control

- 1) There is a regular cleaning service to the premises.
- 2) Regular checks by Caretakers minimise risk of waste accumulation.
- 3) There is an 'Out of Hours' service in place to remove bulk items.
- 4) Bins are located close to the building however the site perimeter does limit the potential bin positions. Email sent to housing manager raising this issue and requesting residents are requested to close bin lids after use as found open.



**Section
16**

Control and Supervision of Contractors and Visitors

- 1) Responsive Repairs service delivered by Sandwell MBC necessitates the production of an order via the computerised repairs system. Details of any known risks are documented on the repair order.
 - 2) Hot works are not permitted unless authorisation is given via the approved officer. The hot works procedure is to be followed.
 - 3) Owing to the nature of Low-Rise flatted accommodation, it is difficult to manage / control individual contractors / utility companies.
 - 4) However, utility companies are not allowed to access any service cupboard or secure area. They must request and collect maintenance keys from the local housing team. This allows scrutiny of what is the scope of any works such as installation of tenant's broadband / phone line etc.
 - 5) Where contractors are appointed to undertake major refurbishment works, Sandwell MBC Urban Design team will put control measures in place. Such Measures include: -
 - a) Pre-Contract Meetings – where contractor is made aware of all working arrangements and safe systems of work to be adopted. Issues covered in this meeting will include:
 - Health and Safety.
 - Site security.
 - Safety of working and impact on children/school business.
 - Fire risk, if any.
 - Site Emergency Plan.
 - b) Monthly Site Meetings – in order to monitor, review and share any new information including any new risks.
 - c) Site monitored daily whilst work is in progress by Clerk of Works / Health and Safety Officers.
 - d) Final Contractor review on completion of works undertaken.
-

Section

17

Arson Prevention

- 1) Regular checks are undertaken by Janitorial / Cleaning Teams which helps reduce the risk of arson.
- 2) There is current evidence of historic arson. Email sent to housing Manager.



- 3) The perimeter of the premises is well illuminated.
 - 4) There have been no fire related incidents since the previous FRA.
-

Section
18

Storage Arrangements

- 1) Residents instructed not to bring L.P.G cylinders into block.
 - 2) The tenancy conditions, Section 7 – Condition 5.6 stipulates “If you live in a flat or maisonette, you, people living with you and any visitors to your property must not keep or use paraffin oil, petrol, bottled gas appliances or any other explosive, FLAMMABLE or dangerous material in the property. This restriction also applies to any storage facility situated in or attached to the block, which has been provided for your use.”
 - 3) No Flammable liquids stored on site by Caretakers / cleaners.
 - 4) There are no flammable liquids or gas cylinders stored on site.
-

Section
19

Additional Control Measures. Fire Risk Assessment - Action Plan

Significant Findings

Action Plan

It is considered that the following recommendations should be implemented to reduce fire risk to, or maintain it at, the following level:

Trivial Tolerable

Definition of priorities (where applicable):

P1 Arrange and complete as urgent – Within 10 days

P2 Arrange and complete within 1-3 Months of assessment date

P3 Arrange and complete within 3-6 Months of assessment date

P4 Arrange and complete exceeding 6 months under programmed work



Fire Risk Assessment Action Plan



Name of Premises or Location:

Waterside 1-10

Date of Action Plan:

02/10/2024

Review Date:

<Insert date>

Question/ Ref No	Required Action	Supporting photograph	Priority	Timescale and Person Responsible	Date Completed
	No Actions				

When undertaking future improvement program(s), it is advised that the observations listed below should be given consideration (noting that the safety of the residents is not jeopardised by these, and all steps to reduce any known risks have been taken).

Observations

Future works programme should consider replacing the nominal fire doors onto the rear deck access with certified self-closing FD 30S door sets.



Future work programme should consider replacing the notional cupboard doors within the staircase to certified FD 30S door sets.



Future work programme should consider replacing the staircase windows, at high level, with opening lights for staircase ventilation purposes.





Fire Risk Assessment

Future work programme should consider an emergency lighting installation to the open deck and staircase.



Signed

	Fire Risk Assessor	Date: 02/10/2024
 Adeiran Jones	Quality Assurance Check	Date: 07/11/2024



Significant Hazards on Site and Information to be Provided for the Fire Service




Name of property: Waterside 1-10

Updated: 09/11/2016

Premise Manager: Tony Thompson

Tel. No.: 0121 569 2975

Hazard	Information/Comments
Asbestos	An asbestos survey has been undertaken of the communal areas. Survey held by Sandwell Housing (Derek Still Tel:- 0121 569 5077). <i>Include survey</i>

Asbestos Survey		Property Address	1-10 Waterside, Great Barr, B43 5PQ		Office use <input checked="" type="checkbox"/>					
Surveyed by	JOHN DAVIS	Date	27/07/16		Checked by	DEREK STILL	Desktop Check	<input checked="" type="checkbox"/>	Site Check	<input type="checkbox"/>
Reason for request		HSG 264 - Survey Report Type		Date		22/05/2020		 Year Built: 1968		
Investment Void		Refurbishment Survey		Property Description		FOUR STOREY MEDIUM RISE BLOCK				
Investment Tenanted		Management Survey								<input checked="" type="checkbox"/>
R & M Void		SHAPE Interrogated.		<input checked="" type="checkbox"/>						
R & M Tenanted		No Existing SHAPE Data.		<input type="checkbox"/>						
Medical / Emergency - Heating Works		Existing SHAPE Data.		<input checked="" type="checkbox"/>						
Communal Areas	<input checked="" type="checkbox"/>	Refurb Surveys Interrogated ?		<input type="checkbox"/>						
						Notes / including details of similar property surveys completed. **This survey is for communal areas only – please see asbestos reports for individual dwellings for any further information** REVIEWED BY S.HARRISON / DON WEBB ON 09/11/2016.				
Building Surveyors 0121 569 5077						Asset Team – Investment Division Operations & Development Centre Roway Lane Oldbury B69 3ES 				

Fire Risk Assessment

Sample Locations	Property Address	1-10 Waterside, Great Barr, B43 5PQ						
LOCATION	MATERIAL	QTY	SURFACE TREATMENT	SAMPLE REF	RESULT	HSE NOTIFY	Labelled	ACTION TAKEN ON CONTRACT
IF DURING THE COURSE OF WORK SUSPECTED ACM'S ARE IDENTIFIED THAT ARE NOT CONTAINED WITHIN THIS REPORT STOP WORK & SEEK ADVICE								
SIDE STAIRWELL WALLS	TEXTURED COATING	-	PAINT SEALED	JD 725 / 001	NONE DETECTED	NO	NO	
SIDE STAIRWELL CEILINGS	TEXTURED COATING	-	PAINT SEALED	JD 725 / 002	NONE DETECTED	NO	NO	
2 ND FLOOR DECK ACCESS WALKWAY FLOOR	ASPHALT	-	SEALED	-	NOT SAMPLED	-	-	PLEASE REQUEST SAMPLE IF TO BE DISTURBED
ITEMS SHOWN BELOW HAVE BEEN ASSESSED ON SITE BY THE ASBESTOS SURVEYOR & ARE CONFIRMED NOT TO BE ACM's.								
LOCATION DESCRIPTION	MATERIAL	LOCATION DESCRIPTION	MATERIAL	LOCATION DESCRIPTION	MATERIAL			
SIDE STAIRWELL ENTRANCE SOFFIT	PLASTIC							
SIDE STAIRWELL ROOF SOFFIT	PLASTIC							
CEILING PANEL TO TOP FLOOR OF STAIRWELL	STERLING BOARD							
SIDE STAIRWELL TRUNKING	METAL							